

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/6	MAKE	CAT	MODEL	910M
SERIAL	CAT0910MKH2201167			STAMP	CAT0910MKH2201167
HR METER	701	HR	Odometer	3279	km
YEAR	2019		YR		
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24 10PR

ENGINE : MODEL		C4.4	S/N
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	A LITTLE · MIDDLE · SEVERE	
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	☒ YES	☐ NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	☒ PS	☐ DD	
Transmission	☒ FAIR	Attn	
Travel	☒ FAIR	Attn	
FOOT BRAKE	☒ FAIR	Attn	
PARKING BRAKE	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY	
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C ·	H/C · H only · C only · None	
FRONT & CYLINDERS			
Arm	☒ FAIR	Attn	
Bell crank	☒ FAIR	Attn	
Bucket	☒ FAIR	Attn	
Articulate	☒ FAIR · ☒ Attn	左右シリンダーにじみあり CYLINDERS: OIL OOZING	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	☒ FAIR · ☐ WORN · ☐ UNEVEN WEAR
COMMENT	
STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING	
RIDE CONTROL	☒ YES · ☐ NO
ATTACHMENTS	
STD BKT	☒ YES · ☐ OTHER
BLADE	☒ YES · ☐ NO Piping for Tilt ☒ YES · ☐ NO
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。