

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/16	MAKE	CAT	MODEL	312D
SERIAL	CAT0312DCFBJ04436		STAMP	CAT0312DCFBJ04436	
HR METER	7518	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		S/N	JKH22284
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		
MAIN PUMP			
Sound	FAIR · Attn		
Oil leakage	FAIR · Attn		
Power	FAIR · Attn		
COOLING SYSTEM			
Radiator	FAIR · Attn		
Oil Cooler	FAIR · Attn		
OPERATING SYSTEM			
Swing	FAIR · Attn	ゴリゴリ感あり RATTLING	
Travel	FAIR · Attn	HI/LO切替え不良 HI/LO SWITCH: MALFUNCTION	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN · FAIR · DIRTY		
Operator's Seat	FAIR · Attn		
Glasses	FAIR · Attn		
AirCon	A/C · H/C · H only · C only · None		
BOOM / ARM / BKT			
Boom	FAIR · Attn		
Boom Cylinder	FAIR · Attn		
Arm	FAIR · Attn		
Arm Cylinder	FAIR · Attn		
ATTACHMENT	FAIR · Attn		
BKT Cylinder	FAIR · Attn		

UNDERCARRIAGE : See Photos. 写真参照		3
COMMENT		
BKT (STD / SLOPE / NARROW / SKELETON / OTHER ()		
Lever	LONG ▪ (WRIST)	
Multi	(MULTI) ▪ 2 ▪ NO	
ARM-CRANE	(YES) ▪ NO	
BLADE	YES ▪ (NO)	
OFFSET	YES ▪ (NO)	
OFFSET Cylinder	FAIR ▪ Attn	
Piping	YES ▪ (NO)	Breaker only ▪ Multi
COMMENT		
リリース掛けるとエンストする		
ENGINE STALLING WITH ENGINE LOAD INCREASING		
アーム動作: レバーを倒してから動くまでワンテンポ遅れる		
ARM: DULL MOVING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。