

INSPECTION SHEET 検品書
FORK LIFT フォークリフト

INSPECTION DATE	2025/10/14	MAKE	KOMATSU	MODEL	FH70-2
SERIAL	51303		STAMP	UNKNOWN	
HR METER	8562	HR	Odometer	-	km YEAR YR
CAB/CNP	CAB	/	CNP	/	NONE
TIRE SIZE	8.25-15				
MAX LIFTING HEIGHT	4.0	m	VIEW	MONO	FORK LENGTH 1200 mm
FORK SPEC					

ENGINE : MODEL 4D95LE-6 S/N 734022	UNDERCARRIAGE : See Photos. 写真参照
Oil leakage ☒ FAIR · Attn	RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
Blow-By ☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE	TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR
Sound ☒ FAIR · Attn	COMMENT
Oil ☒ FAIR · Attn	左Fマッドガードボルト外れないため刻印確認不可
Exhaust Color ☒ FAIR · Attn	STAMP: UNKNOWN
US EPA YES ☒ NO	(BOLT FOR FRONT LEFT FENDER MUDGUARD: UNABLE TO TAKE OFF)
OPERATION PUMP	アタッチメント用配管あり W/PIPING
Sound ☒ FAIR · Attn	
Oil leakage ☒ FAIR · Attn	
Power ☒ FAIR · Attn	
COOLING SYSTEM	
Radiator ☒ FAIR · Attn	
Oil Cooler ☒ FAIR · Attn	
TRANSMISSION & TRAVEL	
T/M TYPE ☒ PS · DD	
Transmission ☒ FAIR · Attn	
Travel ☒ FAIR · Attn	
FOOT BRAKE ☒ FAIR · Attn	
PARKING BRAKE ☒ FAIR · Attn 効き甘い BRAKE: LOOSE	
INTERIOR See Photos. 写真参照	
INTERIOR COND. CLEAN · ☒ FAIR · DIRTY	
Operator's Seat ☒ FAIR · Attn	
Glasses ☒ FAIR · Attn	
AirCon ☒ A/C · H/C · H only · C only · None	
HYDRAULICS	
MAST Cylinder ☒ FAIR · Attn	
TILT Cylinder ☒ FAIR · Attn	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。