

INSPECTION SHEET 検品書
TRUCK CRANE / ALL TERRAIN CRANE トラッククレーン / オールテレーンクレーン

INSPECTION DATE	2025/11/5	CATEGORY	TRUCK CRANE / ALL TERRAIN CRANE		
MAKE	SUMITOMO		MODEL	HC-78RM	
SERIAL	HC078-1436		STAMP	HC078-1436	
HR METER	4198 / CHASSIS: 4037	HR	Odometer	41616	km
YEAR			YEAR	YR	
CHASSIS	MODEL	W-KG520TN	No.	00029	TIRE
					F: 13.00-20 R: 11.00-20

ENGINE(CRANE) : MODEL		S/N	680254
Oil leakage	FAIR	Attn	*1
Blow-By	FAIR	Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
ENGINE(CHASSIS) : MODEL		S/N	
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE MIDDLE SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
OPERATION PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Computer	OK	NG	
Swing	FAIR	Attn	
Travel	FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	AT	MT	No. OF GEARS 7 GEARS
Transmission	FAIR	Attn	
No. of DRIVE WHEELS	2	WD	
Travel	FAIR	Attn	
FOOT BRAKE	FAIR	Attn	
PARKING BRAKE	FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	*2
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only NONE

CRANE	
WEIGHT	3.2t × 1, 1.15t × 2, 0.85t × 1
HOOK	35t, 15t, BALL
BOOM	
MAIN BOOM	TOP, BOTTOM, 6m × 3, 3m × 1
BOOM TOTAL	31m
No. of Section	- SECTIONS
TOP SHEAVE	YES NO
JIB	STD PWR
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	1
TIRE WEAR	FAIR WORN UNEVEN WEAR
COMMENT	
シャーシ側A/C: 冷えない、クレーン側ヒーター&クーラー風出ない	
A/C OF CHASSIS CAB: Malfungtion,	
HEATER & COOLER OF CRANE CAB: NOT BLOWING AIR	
OUTRIGGERS	
OUTRIGGERS	FAIR Attn H-TYPE
FRONT JACK	YES NO
COMMENT	
左側Fアウトリガー近くの配管油漏れ小	
SOME PIPE AROUND FRONT LEFT OUTRIGGER: OIL LEAKING	
クレーン側E/Gストップ: 外部針金を引く	
NEED TO PULL THE ENGINE STOP WIRE TO STOP THE ENGINE OF CRANE	
35tフック、ボールフック、6mブーム×3, 3mブーム×1、	
3.2tウエイト×1, 1.15tウエイト×2: 別置き	
35t HOOK, BALL HOOK, 6m BOOM×3, 3m BOOM×1,	
3.2t WEIGHT×1, & 1.15t WEIGHT×2: NOT ATTACHED	
*1 E/Gブロック合わせ面よりにじみあり	
*1 CONNECTING PART BETWEEN ENGINE BLOCK & MAIN PUMP:	
OIL OOZING	
*2 クレーン側破れ大、シャーシ側破れあり	
*2 CRANE SEAT: A LITTLE DAMAGED, CHASSIS SEAT: CUTS	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。