

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/28	MAKE	KATO	MODEL	KR25H-V7
SERIAL No.	PLATE : 5110483		STAMP : KRC005-0483		
HR METER	23221	HR	Odometer	78896	km
TIRE SIZE	385/95R25		YEAR	2008	YR

ENGINE : MODEL		S/N
Oil leakage	(FAIR) • Attn	
Blow-By	(FAIR) • Attn	A LITTLE • MIDDLE • SEVERE
Sound	(FAIR) • Attn	
Oil	(FAIR) • Attn	
Exhaust Color	(FAIR) • Attn	
OPERATION PUMP		
Sound	(FAIR) • Attn	
Oil leakage	(FAIR) • Attn	
Power	(FAIR) • Attn	
COOLING SYSTEM		
Radiator	(FAIR) • Attn	
Oil Cooler	(FAIR) • Attn	
OPERATING SYSTEM		
Computer	(OK) • NG	
Swing	(FAIR) • Attn	
Travel	(FAIR) • Attn	
TRANSMISSION		
Transmission	(FAIR) • Attn	
No. OF GEARS	4	GEARS
4WD	(4WD) • 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN • (FAIR) • DIRTY	
Operator's Seat	(FAIR) • Attn	
Glasses	(FAIR) • Attn	
AirCon	(A/C) • H/C • H only • C only • None	
COMMENT		

BOOM

No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	(FAIR) ▪ Attn	
DERRICKING CYL.	(FAIR) ▪ Attn	
EXTENSION CYL.	(FAIR) ▪ Attn	
JIB	(YES) ▪ NO	
JIB TYPE	STD ▪ (PWR)	
MAIN & SUB WIRE	(YES) ▪ NO *1	
FREE FALL	YES ▪ (NO)	
HOOK	25t, BALL	
UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	3	
TIRE WEAR	FAIR ▪ WORN (UNEVEN WEAR)	
COMMENT		
OUTRIGGERS		
OUTRIGGERS	X ▪ (H)	
OUTRIGGERS COND.	(FAIR) ▪ Attn	
Oil leakage (JACK CYL.)	FRONT L ▪ R	REAR L ▪ R
Oil leakage (SLIDE CYL.)	FRONT L ▪ R	REAR L ▪ R
COMMENT		
*1 主巻ワイヤーキンクあり MAIN WIRE: KINKED		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		
2		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。