

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/28	MAKE	KATO	MODEL	KR-25H-V7
SERIAL No.	PLATE :	5110327	STAMP :	KRC005-0327	
HR METER	23956	HR	Odometer	80078	km
TIRE SIZE	385/95R25	YEAR	2008	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	

OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	

COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	

OPERATING SYSTEM		
Computer	☒ OK · NG *1	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	

TRANSMISSION		
Transmission	☒ FAIR · Attn	
No. OF GEARS	4 GEARS	
4WD	☒ 4WD · 6WD	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None

COMMENT	

BOOM		
No. of Section	4 SECTIONS	
CRACK/ENFORCEMENT	☒ FAIR · Attn	
DERRICKING CYL.	☒ FAIR · Attn	
EXTENSION CYL.	☒ FAIR · Attn	
JIB	☒ YES · NO	
JIB TYPE	STD · ☒ PWR	
MAIN & SUB WIRE	☒ YES · NO	
FREE FALL	YES · ☒ NO	
HOOK	25t, BALL	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)	3
TIRE WEAR	FAIR · ☒ WORN · UNEVEN WEAR

COMMENT	

OUTRIGGERS				
OUTRIGGERS	☒ X · H			
OUTRIGGERS COND.	FAIR · ☒ Attn	*2		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R

COMMENT	
*1 過巻不良、非常用にて操作可	
*1 OVERWINDING PREVENTION: MALFUNCTION,	
ABLE TO OPERATE IN THE EMERGENCY MODE	
*2 F縦シリンダーロード側取付ピン外れ止め欠、抜け出しあり	
*2 PIN LOCKS OF FRONT JACK CYLINDER RODS:	
MISSING, PINS: SLIPPING OFF	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。