

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/27	MAKE	KATO	MODEL	KR-50H-L
SERIAL No.	PLATE :	4710109	STAMP :	KR511-0109	
HR METER	15477	HR	Odometer	129183	km
TIRE SIZE	505/95R25	YEAR	2001	YR	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR	Attn
Blow-By	☒ FAIR	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR	Attn
Oil	☒ FAIR	Attn
Exhaust Color	☒ FAIR	Attn
OPERATION PUMP		
Sound	☒ FAIR	Attn
Oil leakage	☒ FAIR	Attn
Power	☒ FAIR	Attn
COOLING SYSTEM		
Radiator	☒ FAIR	Attn
Oil Cooler	☒ FAIR	Attn
OPERATING SYSTEM		
Computer	☒ OK	NG
Swing	☒ FAIR	Attn
Travel	☒ FAIR	Attn
TRANSMISSION		
Transmission	☒ FAIR	Attn
No. OF GEARS	4	GEARS
4WD	☒ 4WD	6WD
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR	DIRTY
Operator's Seat	☒ FAIR	Attn
Glasses	☒ FAIR	Attn
AirCon	☒ A/C	H/C · H only · C only · None
COMMENT		

BOOM				
No. of Section	6	SECTIONS		
CRACK/ENFORCEMENT	☒ FAIR	Attn		
DERRICKING CYL.	☒ FAIR	Attn		
EXTENSION CYL.	☒ FAIR	Attn		
JIB	☒ YES	NO		
JIB TYPE	STD	☒ PWR		
MAIN & SUB WIRE	☒ YES	NO		
FREE FALL	YES	☒ NO		
HOOK	51t, 30t, BALL			
UNDERCARRIAGE : See Photos. 写真参照				
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)				1
TIRE WEAR		☒ FAIR · WORN · UNEVEN WEAR		
COMMENT				
穴あり HUGE HOLES				
OUTRIGGERS				
OUTRIGGERS	X	☒ H		
OUTRIGGERS COND.	☒ FAIR	Attn		
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R
COMMENT				
上部カバー穴あり BODY OF UPPER PART: MUCH HOLES				
プライミングポンプ: 燃料漏れあり PRIMING PUMP: FUEL LEAKING				
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。