

INSPECTION SHEET 検品書
ROUGH TERRAIN CRANE ラフタークレーン

INSPECTION DATE	2025/10/28	MAKE	KATO	MODEL	KR-25H-V5
SERIAL No.	PLATE : 5411638			STAMP : KR258-1638	
HR METER	2592	HR	Odometer	3889	km
TIRE SIZE	385/95R25			YEAR	2005 YR

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · ☒ A LITTLE · ☒ MIDDLE · ☐ SEVERE	
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
OPERATION PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Computer	☒ OK · NG	
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
TRANSMISSION		
Transmission	☒ FAIR · ☒ Attn	*1
No. OF GEARS	4 GEARS	
4WD	☒ 4WD · 6WD	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☒ FAIR · Attn	
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
COMMENT		

BOOM					
No. of Section	4	SECTIONS			
CRACK/ENFORCEMENT	☒ FAIR · Attn				
DERRICKING CYL.	☒ FAIR · Attn				
EXTENSION CYL.	☒ FAIR · Attn				
JIB	☒ YES · NO				
JIB TYPE	STD · ☒ PWR				
MAIN & SUB WIRE	☒ YES · NO				
FREE FALL	☒ YES · NO				
HOOK	25t, BALL				
UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 2: CORRODED)					2
TIRE WEAR	FAIR · ☒ WORN · UNEVEN WEAR				
COMMENT					
OUTRIGGERS					
OUTRIGGERS	X · ☒ H				
OUTRIGGERS COND.	☒ FAIR · Attn				
Oil leakage (JACK CYL.)	FRONT	L · R	REAR	L · R	
Oil leakage (SLIDE CYL.)	FRONT	L · R	REAR	L · R	
COMMENT					
ウインチモーター下付近ホース油漏れあり					
SOME HOSE AROUND BOTTOM OF WINCH MOTOR: OIL LEAKING					
*1 トルクコン下油漏れあり BOTTOM OF TORQUE CONVERTER: OIL LEAKING					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。