

INSPECTION SHEET 検品書
ROLLER ローラー

INSPECTION DATE	2025/10/1	MAKE	DYNAPAC	MODEL	CP20W
SERIAL	10253	STAMP	CP20W-10253		
HR METER	UNKNOWN	HR	Odometer	24899	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	15.0-20	YEAR	YR

ENGINE : MODEL		S/N		UNDERCARRIAGE : See Photos. 写真参照	
Oil leakage	FAIR · Attn			RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		TIRE WEAR FAIR · WORN · UNEVEN WEAR	
Sound	FAIR · Attn			COMMENT	
Oil	FAIR · Attn			HRメーターなし NO HR METER	
Exhaust Color	FAIR · Attn			ELECTROLYTEランプ点灯あり WARNING LAMP FOR ELECTROLYTE: ON	
US EPA	YES · NO			*1 左ドア下側割れあり LEFT LOWER DOOR GLASS: CRACKED	
OPERATION PUMP				*2 散水不可(給水タンク左側ドレーンメクラ破損あり、	
Sound	FAIR · Attn			水溜まらない、給水ポンプ呼び水キャップ欠、	
Oil leakage	FAIR · Attn			散水ホースひび割れ多数、亀裂あり、散水フィルター欠)	
Power	FAIR · Attn			*1 NOT WATERING (LEFT DRAIN CAP OF WATER TANK: BROKEN,	
COOLING SYSTEM				UNABLE TO STORE ANY WATER, PRIMING CAP: MISSING,	
Radiator	FAIR · Attn			WATER HOSE: CUT & MUCH CRACKED, WATER FILTER: MISSING)	
Oil Cooler	FAIR · Attn				
TRANSMISSION & TRAVEL					
T/M TYPE	PS · DD				
Transmission	FAIR · Attn				
Travel	FAIR · Attn				
FOOT BRAKE	FAIR · Attn				
PARKING BRAKE	FAIR · Attn				
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN · FAIR · DIRTY				
Operator's Seat	FAIR · Attn				
Glasses	FAIR · Attn *1				
AirCon	A/C · H/C · H only · C only · None				
OTHERS					
Vibratory	FAIR · Attn				
Watering	FAIR · Attn *2				
Articulate	FAIR · Attn			RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。