INSPECTION SHEET 検品書 CARRY DUMP キャリーダンプ

INSPECTION DATE		2025/9/29		MAKE		IHI	-II		DEL	IC100		
SERIAL	CB000076					STAMP		CB000076			76	
HR METER	1853 HR Odometer					ŀ	km Y	EAR			YR	
CAB/CNP	ROPS CA	AB CAB ROP	PS CNP	/ CNP /	NONE	SHOE		750R		TIRE		
ENGINE: MODEL S/N						MAIN FRAME						
Oil leakage	FAIR · Attn					MAIN FLAME FAIR - Attn						
Blow-By	FAIR · Attn	A LITTLE · MIDD	LE · ;	SEVERE		VESSEL						
Sound	FAIR · Attn					VESSE	L	FAIR •	Attn			
Oil	FAIR · Attn					REAR GATE	TYPE	NC	RMAL)· L-	GATE (FLAT)	
Exhaust Color	FAIR · Attn					REAR GA	ATE	FAIR •	Attn			
US EPA	YES · NO		UNDERCARRIAGE: See Photos. 写真参照									
OPERATION PUMP						RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3						
Sound	FAIR · Attn					TIRE WE	AR	FAI	R • W	ORN • UN	NEVEN WEAR	
Oil leakage	FAIR · Attn					COMMENT	Γ					
Power	FAIR · Attn					E/Gストップ	プ不良	、E/G	ストッフ	プ後付け	あり	
COOLING	SYSTEM					ENGINE STOF	PPER: M	IALFUN	CTION, \	W/RETROF	ITTED ENGINE ST	OPPER
Radiator	FAIR · Attn											
Oil Cooler	FAIR · Attn											
TRANSMISSION & TRAVEL												
T/M TYPE	PS) · DD		No. OF	GEARS 2	GEARS							
Transmission	FAIR · Attn											
Travel	FAIR · Attn											
Swing	FAIR · Attn											
Articulate	FAIR · Attn											
FOOT BRAKE	FAIR · Attn											
PARKING BRAKE	FAIR · Attn											
INTERIOR See Photos. 写真参照												
INTERIOR COND.	CLEAN	· FAIR ·	DIR	rTY								
Operator's Seat	FAIR · Attn											
Glasses	FAIR · Attn											
AirCon	A/C)•	H/C • H only	· C	only · I	None	RUST of BODY	(5: NONE	, 4: A LIT	TLE, 3: M	IDDLE, 2: MU	CH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。