

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/30	MAKE	KOMATSU	MODEL	PC138US
SERIAL	NO PLATE			STAMP	KMTPC189A01027440
HR METER	ERROR		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	510G

ENGINE : MODEL 4D95LE-5 S/N 563415	
Oil leakage	FAIR · Attn *1
Blow-By	FAIR · Attn A LITTLE MIDDLE SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
MAIN PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn *2
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
OPERATING SYSTEM	
Swing	FAIR · Attn ガタあり SWING: LOOSE
Travel	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
BOOM / ARM / BKT	
Boom	FAIR · Attn 補修跡あり REPAIRED
Boom Cylinder	FAIR · Attn *3
Arm	FAIR · Attn パッチ、ガタあり PATCHED, LOOSE
Arm Cylinder	FAIR · Attn
ATTACHMENT	FAIR · Attn
BKT Cylinder	FAIR · Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
スィベル下周り油漏れあり BOTTOM OF SWIVEL: OIL LEAKING	
底板周り油汚れ、おしめあり BOTTOM: OIL STAINS (W/ABSORPTION MAT)	
左キャリアローラー曲がりあり LEFT CARRIER ROLLER: BENT	
BKT STD / SLOPE / NARROW / SKELETON / OTHER ()	
Lever	LONG · WRIST
Multi	MULTI · 2 · NO
ARM-CRANE	YES · NO
BLADE	YES · NO
OFFSET	YES · NO
OFFSET Cylinder	FAIR · Attn
Piping	YES · NO Breaker only · Multi 5
COMMENT	
ブーム下ホース割れあり	
SOME HOSES AROUND LOWER PART OF BOOM: CRACKED	
CABドア閉まらない DOOR: UNABLE TO SHUT	
コントロールバルブ油汚れあり CONTROL VALVE: OIL STAINS	
A/Cエラー表示、異音あり A/C ERROR DISPLAY, A/C: NOISES	
*1 油汚れ、E/G下おしめあり	
*1 OIL STAINS, BOTTOM OF ENGINE: W/ABSORPTION MAT	
*2 ホースにじみあり、油汚れ大	
*2 SOME HOSE: OIL OOZING, MUCH OIL STAINS	
*3 左右油漏れ、左配管補修跡あり	
*3 CYLINDERS: OIL LEAKING, LEFT PIPE: REPAIRED	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
2	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。