INSPECTION SHEET 検品書
OTHER その他

INSPECTION DATE	2025/10/14	CATEGORY	プレートコンパクター PLATE COMPACTOR				
MAKE	MIKASA			MODEL	MVH-100AR		
SERIAL	W6941			STAMP	NOT FOUND		
HR METER	UNKNOWN HR	Odometer	km	YEAR	YR		
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	SHOE		TIRE			

ENGINE	MODEL		S/N		
Oil leakage	FAIR・Attn		Oil	FAIR・Attn	
Blow-By	FAIR・Attn	A LITTLE ・MIDDLE ・SEVERE	Exhaust Color	FAIR・Attn	
Sound	FAIR・Attn		EPA	YES ・NO	

CONDITION	FAIR ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3	TIRE WEAR	FAIR ・WORN・ UNEVEN WEAR
COMMENT			
E/Gスターター用の紐破損あり STARTER ROPE: DAMAGED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3		

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。