

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2025/9/30	MAKE	NAGANO	MODEL	NUL120-6
SERIAL No.	PLATE : 12NU63341			STAMP : 12NU63341	
HR METER	800	HR	Odometer	km	YEAR YR
CHASSIS	MODEL -			No. -	
SHOE	300G PADS			TIRE SIZE	
MAX HIGHT	12.1 m			MAX WEIGHT	200 kg

ENGINE : MODEL D1305 S/N 1GM1198			
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	☒ YES	NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	☒ AT	MT	No. OF GEARS 2 GEARS
Transmission	☒ FAIR	Attn	
4WD	☒ 4WD	2WD	
Travel	☒ FAIR	Attn	
Swing	☒ FAIR	Attn	
FOOT BRAKE	☒ FAIR	Attn	
PARKING BRAKE	☒ FAIR	Attn	
BOOM			
No. of Section	2	SECTIONS	
DERRICKING CYL.	☒ FAIR	Attn	
EXTENSION CYL.	☒ FAIR	Attn	

INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	A/C · H/C · H only · C only · ☒ None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS	X · H
OUTRIGGERS COND.	☒ FAIR · Attn
COMMENT	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。