INSPECTION SHEET 検品書 LIFTING PLATFORM 高所作業車

INSPECTIO	N DATE	2025/10/	2 MAKE	MAKE			MODEL	NUL120-6	
SERIAL No.	PLATE: 12NU63342		STAMP: 12NU63342						
HR METER	119	06 HR	Odometer		-	k	m YEAR		YR
CHASSIS	MODEL –				No. –				
SHOE	300G PADS			TIRE SIZI	E				
MAX HIGHT	12.1 m			MAX WEIG	нт		200	kg	
ENGINE: MODEL D1305 S/N 1GL6404					INTERIOR See Photos. 写真参照				
Oil leakage	FAIR · Attn				INTERIOR COND.	CL	EAN •	FAIR • DIRTY	
Blow-By	FAIR · Attn	A LITTLE • N	IIDDLE · SEV	'ERE	Operator's Seat	FAIR •	Attn		
Sound	FAIR · Attn				Glasses	FAIR •	Attn		
Oil	FAIR · Attn				AirCon	A/C	• H/C	· H only · C only ·(None
Exhaust Color	FAIR) · Attn				UNDERCARRIAGE: See Photos. 写真参照				
US EPA	YES)· NO				RUST (5: NONE	, 4: A LI	TTLE, 3: MIDE	DLE, 2: MUCH, 1: CORRODED)	4
OPERATION PUMP					TIRE WEAR FAIR · WORN · UNEVEN WEAR				
Sound	FAIR · Attn				COMMENT	•			
Oil leakage	FAIR · Attn								
Power	FAIR) · Attn								
COOLING SYSTEM					OUTRIGGE	RS	х • н		
Radiator	FAIR · Attn				OUTRIGGERS (COND.	FAIR • Attn		
Oil Cooler	FAIR · Attn				COMMENT				
TRANSMIS	SSION &	TRAVEL							
T/M TYPE	АТ) мт		No. OF GEARS	2 GEARS					
Transmission	FAIR · Attn								
4WD	4WD · 2WD								
Travel	FAIR · Attn								
Swing	FAIR · Attn								
FOOT BRAKE	FAIR • Attn								
PARKING BRAKE	FAIR • Attn								
воом									
No. of Section 2 SECTIONS									
DERRICKI	NG CYL.	FAIR • Attn							
EXTENSION CYL. FAIR) · Attn					RUST of BODY(5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)				

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine. この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。