

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/15	MAKE	KOMATSU	MODEL	PC35MR-2
SERIAL	6919		STAMP	KMTPC096L05006919	
HR METER	4171 HR		YEAR	YR	
CAB/CNP	ROPS CAB / CAB / <u>ROPS CNP</u> / CNP / NONE		SHOE	300G	

ENGINE : MODEL		3D88E	S/N	02329
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY			
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C ・ H/C ・ H only ・ C only ・ None			
BOOM / ARM / BKT				
Boom	FAIR	Attn	2ピースブーム、ガタあり 2-PIECE BOOM, LOOSE	
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn	ロングアーム LONG ARM	
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。