

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/16	MAKE	KOMATSU	MODEL	PC138US-2
SERIAL	2464		STAMP	PC138US-2464	
HR METER	3546	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		4D102E-1	S/N	26284918
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO	不鮮明 STICKER: UNREADABLE	
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn	増速S/W不良 HI/LO SWITCH: MALFUNCTION	
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn	*1	
AirCon	A/C	H/C	H only	C only · None
BOOM / ARM / BKT				
Boom	FAIR	Attn	2ピースブーム 2-PIECE BOOM	
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn	ガタあり LOOSE	
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT 両側シューリンク固着あり TRACK LINKS: STUCK	
BKT	(STD) / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG ▪ (WRIST)
Multi	MULTI ▪ 2 ▪ (NO)
ARM-CRANE	YES ▪ (NO)
BLADE	YES ▪ (NO)
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	(YES) ▪ NO Breaker only ▪ Multi 5
COMMENT ショートリーチ SHORT REACH E/Gストップ不良 ENGINE STOPPER: MALFUNCTION *1 Fひび割れあり、ドアガラス欠 *1 WINDSHIELD: CRACKED, DOOR GLASS: MISSING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。