

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/17	MAKE	CAT	MODEL	320-07A
SERIAL	CAT00320CHEX00455			STAMP	CAT00320CHEX00455
HR METER	1211	HR	YEAR	YR	
CAB/CNP	☒ ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	600G

ENGINE : MODEL C4.4		S/N W7N29257
Oil leakage	☒ FAIR	Attn
Blow-By	☒ FAIR	A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR	Attn
Oil	☒ FAIR	Attn
Exhaust Color	☒ FAIR	Attn
US EPA	☒ YES	NO
MAIN PUMP		
Sound	☒ FAIR	Attn
Oil leakage	☒ FAIR	Attn
Power	☒ FAIR	Attn
COOLING SYSTEM		
Radiator	☒ FAIR	Attn
Oil Cooler	☒ FAIR	Attn
OPERATING SYSTEM		
Swing	☒ FAIR	Attn
Travel	☒ FAIR	Attn
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · ☒ FAIR ·	DIRTY
Operator's Seat	☒ FAIR	Attn
Glasses	☒ FAIR	Attn
AirCon	☒ A/C ·	H/C · H only · C only · None
BOOM / ARM / BKT		
Boom	☒ FAIR	Attn
Boom Cylinder	☒ FAIR	Attn
Arm	☒ FAIR	Attn
Arm Cylinder	☒ FAIR	Attn
ATTACHMENT	☒ FAIR	Attn
BKT Cylinder	☒ FAIR	Attn

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	STD / SLOPE / NARROW / SKELETON ☒ OTHER)
Lever	LONG · ☒ WRIST
Multi	☒ MULTI · 2 · NO
ARM-CRANE	YES · ☒ NO
BLADE	YES · ☒ NO
OFFSET	YES · ☒ NO
OFFSET Cylinder	FAIR · Attn
Piping	☒ YES · NO Breaker only ☒ Multi
COMMENT	
アタッチメント: ストレンジャーバケット ATTACHMENT: THUMB BUCKET	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。