

INSPECTION SHEET 検品書
WHEEL EXCAVATOR タイヤバックホー

INSPECTION DATE	2025/9/25	MAKE	HITACHI	MODEL	EX125WD-5
SERIAL	11MP005340		STAMP	125W-5340	
HR METER	8544	HR	Odometer	66967	km
YEAR	YR				
CAB/CNP	ROPS CAB / CAB / ROPS		CNP / CNP / NONE	TIRE SIZE	9.00-20 12PR

ENGINE : MODEL		6BG1	S/N
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO		

MAIN PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn 下側にじみあり BOTTOM OF PUMP: OIL OOZING
Power	FAIR	Attn

COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn

OPERATING SYSTEM		
Swing	FAIR	Attn
Travel	FAIR	Attn

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れ、擦れ、汚れあり HUGE CUTS, DIRTY
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

BOOM / ARM / BKT		
Boom	FAIR ・ Attn	
Boom Cylinder	FAIR ・ Attn	
Arm	FAIR ・ Attn	
Arm Cylinder	FAIR ・ Attn	
ATTACHMENT	FAIR ・ Attn	ガタあり LOOSE
BKT Cylinder	FAIR ・ Attn	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR (FAIR) • WORN • UNEVEN WEAR	

COMMENT	

BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()
-----	--

Lever	LONG • WRIST
-------	--------------

Multi	MULTI : 2 : NO
-------	----------------

ARM-CRANE	YES - NO	
-----------	----------	--

ARM STAKE	☒ YES	☐ NO	
BLADE	☒ YES	☐ NO	

BLADE	☒ YES - ☐ NO	
OFFSET	☐ YES - ☒ NO	

OFFSET	YES • NO	

OFFSET Cylinder	FAIR	Attn
-----------------	------	------

Piping	YES	NO	Breaker only	Multi	*1
--------	-----	----	--------------	-------	----

OUTRIGGERS COND.	FAIR	▪ Attn	
------------------	------	--------	--

COMMENT

A/Cスイッチ入らない A/C: UNABLE TO TURN ON

左ミラー割れあり LEFT OUTER REAR-VIEW MIRROR: CRACKED

ラジオ不良 RADIO: MALFUNCTION

*1 配管ペダル操作ロック解除時動作入りっぱなしになるため番線固定あり

*1 PEDAL : FIXED WITH SOME WIRE (ALWAYS WORKING)

	PEDAL FIRED WITH SOME WIRE (NEWHS WORKING)

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
--	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。