

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE	2025/9/29	MAKE	TADANO	MODEL	AT-220-1
SERIAL No.	PLATE : 380860			STAMP : NOT FOUND	
HR METER	6922	HR	Odometer	115167	km
YEAR	YR				
CHASSIS	MODEL TKG-XZU710M			No. XZU710-0008123	
SHOE				TIRE SIZE	215/70R17.5
MAX HIGHT	22.3			m	
MAX WEIGHT	200			kg	

ENGINE : MODEL S/N	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES ☒ NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ AT · MT *1 No. OF GEARS 4 GEARS
Transmission	☒ FAIR · Attn
4WD	4WD ☒ 2WD
Travel	☒ FAIR · Attn
Swing	☒ FAIR · Attn
FOOT BRAKE	☒ FAIR · Attn
PARKING BRAKE	☒ FAIR · Attn
BOOM	
No. of Section	4 SECTIONS
DERRICKING CYL.	☒ FAIR · Attn
EXTENSION CYL.	☒ FAIR · Attn

INTERIOR See Photos. 写真参照	
INTERIOR COND.	☒ CLEAN · FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	☒ FAIR · Attn
AirCon	☒ A/C · H/C · H only · C only · None
UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	☒ FAIR · WORN · UNEVEN WEAR
COMMENT	
OUTRIGGERS X · ☒ H	
OUTRIGGERS COND.	☒ FAIR · Attn
COMMENT	
*1 オーバードライブあり W/OVERDRIVE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。