

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/9/25	MAKE	KOMATSU	MODEL	WA200-1
SERIAL	30651	STAMP	W008-30651		
HR METER	2938	HR	Odometer	42438	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE	TIRE SIZE	17.5-25 12PR (SNOW, SPIKE)	YEAR	YR

ENGINE : MODEL 6D105-1 S/N 111325	
Oil leakage	FAIR · Attn
Blow-By	FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn
Oil	FAIR · Attn
Exhaust Color	FAIR · Attn
US EPA	YES · NO
OPERATION PUMP	
Sound	FAIR · Attn
Oil leakage	FAIR · Attn
Power	FAIR · Attn
COOLING SYSTEM	
Radiator	FAIR · Attn
Oil Cooler	FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	PS · DD
Transmission	FAIR · Attn
Travel	FAIR · Attn
FOOT BRAKE	FAIR · Attn
PARKING BRAKE	FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · FAIR · DIRTY
Operator's Seat	FAIR · Attn *1
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · None
FRONT & CYLINDERS	
Arm	FAIR · Attn *2
Bell crank	FAIR · Attn
Bucket	FAIR · Attn
Articulate	FAIR · Attn *3

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
下周りにじみあり BOTTOM: OIL OOZING	
タコメーター TACHOMETER: 11904km	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER マルチプラウ MULTI PLOW
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
機体外装リペイントあり REPAINTED	
*1 穴、汚れ、左右アームレスト破れあり HOLES, DIRTY, ARMRESTS: CUTS	
*2 左シリンダー油漏れあり LEFT CYLINDER: OIL LEAKING	
*3 左右シリンダーにじみあり CYLINDERS: OIL OOZING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。