

INSPECTION SHEET 検品書
TRUCKトラック

INSPECTION DATE	2025/10/2	MAKE	ISUZU	MODEL	NKR85
SERIAL	7046954			STAMP	NKR85-7046954
HR METER	UNKNOWN	HR	Odometer	250938	km
TIRE	215/70R17.5 (SNOW)			YEAR	YR

ENGINE : MODEL 4JJ1 S/N			
Oil leakage	☒ FAIR	Attn	
Blow-By	☒ FAIR	Attn A LITTLE ・ MIDDLE ・ SEVERE	
Sound	☒ FAIR	Attn	
Oil	☒ FAIR	Attn	
Exhaust Color	☒ FAIR	Attn	
US EPA	YES	☒ NO	
OPERATION PUMP			
Sound	☒ FAIR	Attn	
Oil leakage	☒ FAIR	Attn	
Power	☒ FAIR	Attn	
COOLING SYSTEM			
Radiator	☒ FAIR	Attn	
Oil Cooler	☒ FAIR	Attn	
TRANSMISSION & TRAVEL			
T/M TYPE	AT	☒ MT	No. OF GEARS 6 GEARS
Transmission	☒ FAIR	Attn	
4WD	4WD	☒ 2WD	
Travel	☒ FAIR	Attn 5・6速未確認 5th & 6th GEARS: NOT CHECKED	
FOOT BRAKE	☒ FAIR	Attn	
PARKING BRAKE	☒ FAIR	Attn	
INTERIOR See Photos. 写真参照			
INTERIOR COND.	☒ CLEAN	FAIR ・ DIRTY	
Operator's Seat	☒ FAIR	Attn	
Glasses	☒ FAIR	Attn	
AirCon	☒ A/C	H/C ・ H only ・ C only ・ NONE	
OUTRIGGERS / JACK			
OUTRIGGERS	X	H	
CONDITION	☒ FAIR	Attn	
JACK	☒ FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4
TIRE WEAR	☒ FAIR	☐ WORN ・ UNEVEN WEAR	
COMMENT			
Fアクスルにじみあり FRONT AXLE: OIL OOZING			
BODY			
CATEGORY	パッカー車 GARBAGE TRUCK		
MAKE	KYOKUTO		
MODEL	GB48-27L-S	SERIAL	15R020005M
CONDITION	☒ FAIR	Attn	
MAIN FRAME	☒ FAIR	Attn	
CRANE			
MAKE			
MODEL		SERIAL	
No. of Section	SECTIONS		
HOOK			
RADIO CONTROL	YES	☐ NO	
COMMENT			
バックモニターピント悪い BACK CAMERA: OUT OF FOCUS			
左右押込み板シリンダー油漏れ小			
COMPACTION PLATE CYLINDERS: OIL LEAKING			
最大出力 MAXIMUM OUTPUT: 110kW/2800rpm			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。