

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/9/30	MAKE	YANMAR	MODEL	VIO20-3
SERIAL	3F473			STAMP	3F473
HR METER	3410	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			SHOE	250R

ENGINE : MODEL		S/N	M4677
Oil leakage	FAIR	Attn	
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn	
Oil	FAIR	Attn	
Exhaust Color	FAIR	Attn	
US EPA	YES	NO	
MAIN PUMP			
Sound	FAIR	Attn	
Oil leakage	FAIR	Attn	
Power	FAIR	Attn	
COOLING SYSTEM			
Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	
OPERATING SYSTEM			
Swing	FAIR	Attn	
Travel	FAIR	Attn	*1
INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only · C only · None
BOOM / ARM / BKT			
Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	コンクリート付着小 CONCRETE STAINS
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE :						See Photos.	写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							4
COMMENT							
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()						
Lever	LONG • (WRIST)						
Multi	(MULTI) • 2 • NO						
ARM-CRANE	YES • (NO)						
BLADE	(YES) • NO						
OFFSET	YES • (NO)						
OFFSET Cylinder	FAIR • Attn						
Piping	(YES) • NO	Breaker only		(• Multi)			
COMMENT							
*1 走行モーター一部両側にじみあり TRAVEL MOTORS: OIL OOZING							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。