

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/6	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	20549		STAMP	KMTPC189V01020549	
HR METER	8144	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	700G	

ENGINE : MODEL		S/N
Oil leakage	☒ FAIR · Attn	
Blow-By	☒ FAIR · ☒ Attn	A LITTLE · MIDDLE · ☒ SEVERE *1
Sound	☒ FAIR · Attn	
Oil	☒ FAIR · Attn	
Exhaust Color	☒ FAIR · Attn	
US EPA	YES · ☒ NO	
MAIN PUMP		
Sound	☒ FAIR · Attn	
Oil leakage	☒ FAIR · Attn	
Power	☒ FAIR · Attn	
COOLING SYSTEM		
Radiator	☒ FAIR · Attn	
Oil Cooler	☒ FAIR · Attn	
OPERATING SYSTEM		
Swing	☒ FAIR · Attn	
Travel	☒ FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · ☒ DIRTY	
Operator's Seat	☒ FAIR · Attn	破れあり TORN
Glasses	☒ FAIR · Attn	
AirCon	☒ A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	☒ FAIR · Attn	
Boom Cylinder	FAIR · ☒ Attn	右側油漏れあり RIGHT CYLINDER: OIL LEAKING
Arm	☒ FAIR · Attn	
Arm Cylinder	☒ FAIR · Attn	
ATTACHMENT	☒ FAIR · Attn	
BKT Cylinder	☒ FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照		
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		2
COMMENT		
BKT	☒ STD / SLOPE / NARROW / SKELETON / OTHER()	
Lever	LONG · ☒ WRIST	
Multi	☒ MULTI · 2 · NO	
ARM-CRANE	YES · ☒ NO	
BLADE	YES · ☒ NO	
OFFSET	YES · ☒ NO	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · ☒ NO Breaker only · Multi	
COMMENT		
Hリンク:ガタあり H-LINK: LOOSE		
*1 オイル吐出しあり OIL SPURTING		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		1

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。