

INSPECTION SHEET 検品書
CRAWLER DRILL クローラドリル

INSPECTION DATE		2025/10/28		MAKE	ATLAS COPCO		MODEL	CDH-830C/03	
SERIAL	W008062BO				STAMP	W008062BO			
HR METER	7729			HR	YEAR	YR			
CAB/CNP	CAB	/	CNP	/	NONE	SHOE	330G		
DRIFTER MODEL		YH-70-0703806							

ENGINE : MODEL		QSB5.9	S/N	46776565
Oil leakage	FAIR・Attn	にじみあり OIL OOZING		
Blow-By	FAIR・Attn	A LITTLE・MIDDLE・SEVERE		
Sound	FAIR・Attn			
Oil	FAIR・Attn			
Exhaust Color	FAIR・Attn			
US EPA	YES・NO			
MAIN PUMP				
Sound	FAIR・Attn			
Oil leakage	FAIR・Attn			
Power	FAIR・Attn			
COOLING SYSTEM				
Radiator	FAIR・Attn			
Oil Cooler	FAIR・Attn			
OPERATING SYSTEM				
Swing	FAIR・Attn			
Travel	FAIR・Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN・FAIR・DIRTY			
Operator's Seat	FAIR・Attn	破れあり MUCH CRACKED		
Glasses	FAIR・Attn			
AirCon	A/C・H/C・H only・C only・None			
DRIFTER HYDR.				
Lift	FAIR・Attn			
Swing	FAIR・Attn	*1		
Tilt	FAIR・Attn	*2		
Slide	FAIR・Attn	油汚れあり OIL STAINS		

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT	
Guide(Slide Length)	4000 mm
Rod Changer	YES ☒ NO
Drifter	YES ☒ NO
Compressor	YES ☒ NO エアー漏れあり AIR LEAKING
Blow	YES ☒ NO
COMMENT	
ドリル周りホースヒビ多数あり	
SOME HOSES AROUND DRILL: MUCH CRACKED	
スライドフロント部シリンダー左右油漏れ小、左側シリンダーサビあり	
CYLINDERS OF FRONT PART OF SLIDE: OIL LEAKING, LEFT CYLINDER: RUSTY	
*1 ブームスイングシリンダー油漏れあり(メクラ処理しているため動かない)	
*1 BOOM SWING CYLINDER: OIL LEAKING (W/CAPS)	
*2 油漏れあり(メクラ処理しているため動かない) OIL LEAKING (W/CAPS)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。