

INSPECTION SHEET 検品書
LIFTING PLATFORM 高所作業車

INSPECTION DATE		2025/10/2		MAKE		AICHI		MODEL		SP21A	
SERIAL No.	PLATE : 730723					STAMP : NOT FOUND					
HR METER	7396		HR	Odometer		- km			YEAR	YR	
CHASSIS	MODEL -					No. -					
SHOE						TIRE SIZE		9.00-20/7.00 SOLID			
MAX HIGHT	21.0 m					MAX WEIGHT		200 kg			

ENGINE :		MODEL	4LE2	S/N	241551
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE ▪ MIDDLE ▪ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
OPERATION PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	AT ▪ MT		No. OF GEARS	GEARS	
Transmission	FAIR	Attn			
4WD	4WD ▪ 2WD				
Travel	FAIR	Attn			
Swing	FAIR	Attn			
FOOT BRAKE	FAIR	Attn			
PARKING BRAKE	FAIR	Attn			
BOOM					
No. of Section	3	SECTIONS			
DERRICKING CYL.	FAIR	Attn	油漏れ小 OIL LEAKING		
EXTENSION CYL.	FAIR	Attn			

INTERIOR		See Photos. 写真参照	
INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None
UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
TIRE WEAR	FAIR	WORN	UNEVEN WEAR
COMMENT			
ステアリングシリンダー油漏れあり STEERING CYLINDER: OIL LEAKING			
OUTRIGGERS	X	H	
OUTRIGGERS COND.	FAIR	Attn	
COMMENT			
バケット変形あり BUCKET: DEFORMED			
ブームカバー: パッチあり BOOM COVER: PATCHED			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。