

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/9/29	MAKE	KOMATSU	MODEL	WA100-1
SERIAL	34635			STAMP	W005-34635
HR METER	10807	HR	Odometer	-	km YEAR YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24

ENGINE : MODEL 6D95L S/N 111849 Oil leakage ☒ FAIR · Attn Blow-By ☒ FAIR · ☒ A LITTLE ☒ MIDDLE · SEVERE Sound ☒ FAIR · Attn Oil ☒ FAIR · Attn Exhaust Color ☒ FAIR · Attn US EPA YES · ☒ NO OPERATION PUMP Sound ☒ FAIR · Attn Oil leakage ☒ FAIR · Attn Power ☒ FAIR · Attn COOLING SYSTEM Radiator ☒ FAIR · Attn Oil Cooler ☒ FAIR · Attn TRANSMISSION & TRAVEL T/M TYPE ☒ PS · DD Transmission ☒ FAIR · Attn Travel ☒ FAIR · Attn FOOT BRAKE ☒ FAIR · Attn PARKING BRAKE ☒ FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · ☒ FAIR · DIRTY Operator's Seat ☒ FAIR · Attn アームレスト破損あり ARMRESTS: DAMAGED Glasses ☒ FAIR · Attn AirCon A/C · H/C · ☒ H only · C only · None FRONT & CYLINDERS Arm ☒ FAIR · Attn Bell crank ☒ FAIR · Attn Bucket ☒ FAIR · ☒ *1 Articulate ☒ FAIR · Attn ガタ小 LOOSE	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR COMMENT STEERING TYPE ☒ WHEEL STEERING / ☒ COMMAND STEERING / LEVER STEERING RIDE CONTROL YES · ☒ NO ATTACHMENTS STD BKT YES · ☒ OTHER スノーブレード SNOW BLADE BLADE YES · ☒ NO Piping for Tilt ☒ YES · NO COMMENT *1 左アングルシリンダーにじみ、スノーブレードスライド部ガタあり *1 LEFT ANGLE CYLINDER: OIL OOZING, SLIDE PART OF SNOW BLADE: LOOSE RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
--	--

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。