

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/9/30	MAKE	CAT	MODEL	910H		
SERIAL	CAT0910HESAT01750			STAMP	CAT0910HESAT01750		
HR METER	1943	HR	Odometer	–	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	16.9-24 (SNOW, SPIKE)		

ENGINE :	MODEL	C4.4	S/N	C4E25582
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

FRONT & CYLINDERS

Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

TIRE WEAR (FAIR - WORN - UNEVEN WEAR)

COMMENT

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	☒ YES	☐ NO
--------------	--------------------------------------	--------------------------

ATTACHMENTS

STD BKT	YES	<u>OTHER</u>	マルチプラウ MULTI PLOW
BLADE	YES	<u>NO</u>	Piping for Tilt <u>YES</u> • NO

COMMENT

クーラー冷えない COOLER: MALFUNCTION

This image shows a blank sheet of white paper with horizontal ruling lines. A solid black vertical line runs down the left side, creating a margin. The rest of the page is filled with evenly spaced horizontal black lines. There are no markings or text on the page.

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。