

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/6	MAKE	KOBELCO	MODEL	LK300		
SERIAL	RL-03977		STAMP	LK302-3977			
HR METER	7332	HR	Odometer	-	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		TIRE SIZE	16.9-24			

ENGINE : MODEL						S/N								
Oil leakage		(FAIR) · Attn												
Blow-By		(FAIR) · Attn		A LITTLE · MIDDLE · SEVERE										
Sound		(FAIR) · Attn												
Oil		(FAIR) · Attn												
Exhaust Color		(FAIR) · Attn												
US EPA		YES · (NO)												
OPERATION PUMP														
Sound		(FAIR) · Attn												
Oil leakage		(FAIR) · Attn												
Power		(FAIR) · Attn												
COOLING SYSTEM														
Radiator		(FAIR) · Attn												
Oil Cooler		(FAIR) · Attn												
TRANSMISSION & TRAVEL														
T/M TYPE		(PS) · DD												
Transmission		(FAIR) · Attn												
Travel		(FAIR) · Attn												
FOOT BRAKE		(FAIR) · Attn												
PARKING BRAKE		(FAIR) · Attn												
INTERIOR See Photos. 写真参照														
INTERIOR COND.		CLEAN · (FAIR) · DIRTY												
Operator's Seat		(FAIR) · Attn		破れあり HUGE CUTS										
Glasses		(FAIR) · Attn												
AirCon		A/C · H/C · (H only) · C only · None												
FRONT & CYLINDERS														
Arm		(FAIR) · (Attn)		*1										
Bell crank		(FAIR) · Attn												
Bucket		(FAIR) · (Attn)		にじみあり OIL OOZING										
Articulate		(FAIR) · Attn		ガタあり LOOSE										
UNDERCARRIAGE : See Photos. 写真参照														
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										2				
TIRE WEAR (FAIR) · WORN · UNEVEN WEAR														
COMMENT ミッション周りホース油漏れあり SOME PIPE AROUND TRANSMISSION: OIL LEAKING														
STEERING TYPE (WHEEL STEERING / COMMAND STEERING / LEVER STEERING)														
RIDE CONTROL YES · (NO)														
ATTACHMENTS														
STD BKT (YES) · OTHER														
BLADE YES · (NO)								Piping for Tilt		YES · (NO)				
COMMENT *1 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING														
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)														
2														

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。