

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/27	MAKE	TCM	MODEL	L27-3
SERIAL	RYU4G000V00002393			STAMP	S32-02393
HR METER	24360	HR	Odometer	—	km
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	20.5-25 6PR

ENGINE : MODEL S/N Oil leakage ☐ FAIR · Attn Blow-By ☐ FAIR · Attn A LITTLE · MIDDLE · SEVERE Sound ☐ FAIR · Attn Oil ☐ FAIR · Attn Exhaust Color ☐ FAIR · Attn US EPA YES · ☒ NO OPERATION PUMP Sound ☐ FAIR · Attn Oil leakage ☐ FAIR · Attn Power ☐ FAIR · Attn COOLING SYSTEM Radiator ☐ FAIR · Attn Oil Cooler ☐ FAIR · Attn TRANSMISSION & TRAVEL T/M TYPE ☒ PS · DD Transmission ☐ FAIR · ☒ Attn 油漏れ小 OIL LEAKING Travel ☐ FAIR · Attn FOOT BRAKE ☐ FAIR · Attn PARKING BRAKE ☐ FAIR · Attn INTERIOR See Photos. 写真参照 INTERIOR COND. CLEAN · FAIR · ☒ DIRTY Operator's Seat ☐ FAIR · Attn Glasses ☐ FAIR · Attn AirCon ☒ A/C · H/C · H only · C only · None FRONT & CYLINDERS Arm ☐ FAIR · Attn Bell crank ☐ FAIR · Attn Bucket ☐ FAIR · Attn Articulate ☐ FAIR · ☒ Attn ガタあり LOOSE	UNDERCARRIAGE : See Photos. 写真参照 RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3 TIRE WEAR ☒ FAIR · WORN · UNEVEN WEAR COMMENT STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING RIDE CONTROL YES · ☒ NO ATTACHMENTS STD BKT ☒ YES · OTHER BLADE YES · ☒ NO Piping for Tilt YES · ☒ NO COMMENT 上下小さな右サイドカバー欠品あり UPPER & LOWER COVERS OF RIGHT SIDE BODY: MISSING RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) 3
---	---

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
 この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。