

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |            |           |
|-----------------|----------------------------------------|------|---------|------------|-----------|
| INSPECTION DATE | 2025/9/30                              | MAKE | KOBELCO | MODEL      | SK235SR-2 |
| SERIAL          | YF05-02138                             |      | STAMP   | YF05-02138 |           |
| HR METER        | 8647                                   | HR   | YEAR    | YR         |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 700G       |           |

|                           |       |                              |                                   |
|---------------------------|-------|------------------------------|-----------------------------------|
| ENGINE : MODEL            |       | J05E                         | S/N                               |
| Oil leakage               | FAIR  | Attn                         |                                   |
| Blow-By                   | FAIR  | Attn                         | A LITTLE · MIDDLE · SEVERE        |
| Sound                     | FAIR  | Attn                         |                                   |
| Oil                       | FAIR  | Attn                         |                                   |
| Exhaust Color             | FAIR  | Attn                         |                                   |
| US EPA                    | YES   | NO                           |                                   |
| MAIN PUMP                 |       |                              |                                   |
| Sound                     | FAIR  | Attn                         |                                   |
| Oil leakage               | FAIR  | Attn                         |                                   |
| Power                     | FAIR  | Attn                         |                                   |
| COOLING SYSTEM            |       |                              |                                   |
| Radiator                  | FAIR  | Attn                         |                                   |
| Oil Cooler                | FAIR  | Attn                         |                                   |
| OPERATING SYSTEM          |       |                              |                                   |
| Swing                     | FAIR  | Attn                         | ガタ、ゴリゴリ感あり SWING: LOOSE, RATTLING |
| Travel                    | FAIR  | Attn                         |                                   |
| INTERIOR See Photos. 写真参照 |       |                              |                                   |
| INTERIOR COND.            | CLEAN | FAIR                         | DIRTY                             |
| Operator's Seat           | FAIR  | Attn                         | 損傷あり A LITTLE DAMAGED             |
| Glasses                   | FAIR  | Attn                         |                                   |
| AirCon                    | A/C   | H/C · H only · C only · None |                                   |
| BOOM / ARM / BKT          |       |                              |                                   |
| Boom                      | FAIR  | Attn                         |                                   |
| Boom Cylinder             | FAIR  | Attn                         | 左側にじみあり LEFT CYLINDER: OIL OOZING |
| Arm                       | FAIR  | Attn                         |                                   |
| Arm Cylinder              | FAIR  | Attn                         |                                   |
| ATTACHMENT                | FAIR  | Attn                         |                                   |
| BKT Cylinder              | FAIR  | Attn                         |                                   |

|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|-----------------------------------------------------------------------------|--|-----------------------------------------------|--|--------------|--|-------------------------|----------|--|----------|--|--|
| <b>UNDERCARRIAGE :</b>                                                      |  |                                               |  |              |  | <b>See Photos. 写真参照</b> |          |  |          |  |  |
| <b>RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b>         |  |                                               |  |              |  |                         | <b>3</b> |  |          |  |  |
| <b>COMMENT</b>                                                              |  |                                               |  |              |  |                         |          |  |          |  |  |
| 左右ピンブッシュ割れ多数あり MANY PIN BUSHES: BROKEN                                      |  |                                               |  |              |  |                         |          |  |          |  |  |
| トラックローラーガタあり SOME TRACK ROLLERS: LOOSE                                      |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
| <b>BKT</b>                                                                  |  | (STD / SLOPE / NARROW / SKELETON / OTHER( ) ) |  |              |  |                         |          |  |          |  |  |
| <b>Lever</b>                                                                |  | LONG ▪                                        |  | (WRIST)      |  |                         |          |  |          |  |  |
| <b>Multi</b>                                                                |  | (MULTI) ▪ 2 ▪ NO                              |  |              |  |                         |          |  |          |  |  |
| <b>ARM-CRANE</b>                                                            |  | (YES) ▪ NO                                    |  | *1           |  |                         |          |  |          |  |  |
| <b>BLADE</b>                                                                |  | YES ▪                                         |  | (NO)         |  |                         |          |  |          |  |  |
| <b>OFFSET</b>                                                               |  | YES ▪                                         |  | (NO)         |  |                         |          |  |          |  |  |
| <b>OFFSET Cylinder</b>                                                      |  | FAIR ▪ Attn                                   |  |              |  |                         |          |  |          |  |  |
| <b>Piping</b>                                                               |  | (YES) ▪ NO                                    |  | Breaker only |  | ▪ Multi                 |          |  |          |  |  |
| <b>COMMENT</b>                                                              |  |                                               |  |              |  |                         |          |  |          |  |  |
| E023、E022表示あり “E023” & “E022” ERRORS DISPLAY                                |  |                                               |  |              |  |                         |          |  |          |  |  |
| リリース掛けるとエンストする                                                              |  |                                               |  |              |  |                         |          |  |          |  |  |
| ENGINE STALLING WITH ENGINE LOAD INCREASING                                 |  |                                               |  |              |  |                         |          |  |          |  |  |
| バックカメラ不良 BACK MONITOR: MALFUNCTION                                          |  |                                               |  |              |  |                         |          |  |          |  |  |
| *1 100%荷重表示消えない “100% LOAD” DISPLAY: NOT DISAPPEARING                       |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
|                                                                             |  |                                               |  |              |  |                         |          |  |          |  |  |
| <b>RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)</b> |  |                                               |  |              |  |                         |          |  | <b>2</b> |  |  |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。