

INSPECTION SHEET 検品書
DUMP TRUCK ダンプ

INSPECTION DATE	2025/9/30	CATEGORY	<u>ON-ROAD DUMP</u> ・ OFF-ROAD DUMP	
MAKE	ISUZU		MODEL	FRR33H2
SERIAL	FRR33H2-3001532		STAMP	FRR33H2-3001532
HR METER	UNKNOWN	HR	ODOMETER	150711 km
TIRE SIZE	8.25R16 14PR (SNOW, STUDLESS)		YEAR	YR

ENGINE : MODEL 6HH1 S/N			
Oil leakage	<u>FAIR</u> ・ Attn		
Blow-By	<u>FAIR</u> ・ Attn	A LITTLE ・ MIDDLE ・ SEVERE	
Sound	<u>FAIR</u> ・ Attn		
Oil	<u>FAIR</u> ・ Attn		
Exhaust Color	<u>FAIR</u> ・ <u>Attn</u>	白煙あり WHITE FUMES	
US EPA	YES ・ <u>NO</u>		
OPERATION PUMP			
Sound	<u>FAIR</u> ・ Attn		
Oil leakage	<u>FAIR</u> ・ Attn		
Power	<u>FAIR</u> ・ Attn		
COOLING SYSTEM			
Radiator	<u>FAIR</u> ・ Attn		
Oil Cooler	<u>FAIR</u> ・ Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	<u>AT</u> ・ <u>MT</u>	No. OF GEARS	6 GEARS
Transmission	<u>FAIR</u> ・ Attn		
4WD	4WD ・ <u>2WD</u>		
Travel	<u>FAIR</u> ・ Attn	5・6速未確認 5th & 6th GEARS: NOT CHECKED	
Articulate	<u>FAIR</u> ・ Attn		
FOOT BRAKE	<u>FAIR</u> ・ Attn		
PARKING BRAKE	<u>FAIR</u> ・ Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN ・ <u>FAIR</u> ・ DIRTY		
Operator's Seat	<u>FAIR</u> ・ <u>Attn</u>	破れあり HUGE CUTS	
Glasses	<u>FAIR</u> ・ Attn		
AirCon	<u>A/C</u> ・ H/C ・ H only ・ C only ・ None		

MAIN FRAME			
MAIN FLAME	<u>FAIR</u> ・ Attn	サビあり RUSTY	
VESSEL			
MAKE	SHIN MAYWA		
VESSEL	<u>FAIR</u> ・ Attn		
REAR GATE TYPE	NORMAL ・ L-GATE (FLAT)		
REAR GATE	<u>FAIR</u> ・ Attn		
UNDERCARRIAGE: See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2
TIRE WEAR	<u>FAIR</u> ・ WORN ・ UNEVEN WEAR		
COMMENT			
ラジオ音出ない RADIO: NOT SPEAKING			
コボレーンS/Wあり(動作しない) AUTO SHEET SWITCH: NOT WORKING			
最高出力 MAXIMUM OUTPUT: 210PS/2850rpm			
最大積載量 MAXIMUM LOAD: 3080kg			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			2

This inspection information is for reference only at “the inspection date” by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。