

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/3	MAKE	YANMAR	MODEL	V4-6		
SERIAL	61269			STAMP	V46-61269		
HR METER	2052	HR	Odometer	—	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	15.5/60-18 8PR (SNOW, SPIKE)		

ENGINE : MODEL		4TNV88	S/N	H4212
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ▪ FAIR ▪ DIRTY				
Operator's Seat	FAIR	▪ Attn			
Glasses	FAIR	▪ Attn			
AirCon	A/C ▪ H/C ▪ H only	▪ C only	▪ None		

FRONT & CYLINDERS

Arm	FAIR · Attn	
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

TIRE WEAR (FAIR • WORN • UNEVEN WEAR)

COMMENT

STEERING TYPE ☒ WHEEL STEERING / ☐ COMMAND STEERING / ☐ LEVER STEERING

RIDE CONTROL	YES	▪	(NO)
--------------	-----	---	------

ATTACHMENTS

STD BKT	☒ YES • ☐ OTHER
---------	--

BLADE	YES	▪	(NO)	Piping for Tilt	YES	▪	(NO)
-------	-----	---	------	-----------------	-----	---	------

COMMENT

機体外装リペイントあり REPAINTED[illegible]

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。