

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/21	MAKE	HITACHI	MODEL	ZX210K-3
SERIAL	HCM1U300A00204981		STAMP	HCM1U300A00204981	
HR METER	8116	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600FLAT	

ENGINE : MODEL		4HK1	S/N	417703
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn		
Travel	FAIR	Attn	*1	
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり TORN	
Glasses	FAIR	Attn	*2	
AirCon	A/C	H/C	H only	C only
None				
BOOM / ARM / BKT				
Boom	FAIR	Attn		
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn		
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn		

UNDERCARRIAGE :						See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							2
COMMENT							
右側シューリンク固着あり RIGHT TRACK LINKS: STUCK							
BKT	STD / SLOPE / NARROW / SKELETON (OTHER)						
Lever	LONG	▪	(WRIST)				
Multi	MULTI	▪	2	▪	(NO)		
ARM-CRANE	YES	▪	(NO)				
BLADE	YES	▪	(NO)				
OFFSET	YES	▪	(NO)				
OFFSET Cylinder	FAIR	▪	Attn				
Piping	(YES)	▪	NO	Breaker only	▪	Multi	4
COMMENT							
アタッチメント:回転式カッター ROTATABLE CUTTER AS SPARE							
クランプアーム付 W/CLAMP ARM							
バッテリーチャージランプ点灯あり CHARGE LAMP: ON							
*1 遅い(増速はする) SLOW TRAVELING (ABLE TO SPEED UP)							
*2 F上部、ドア上部1枚欠							
*2 UPPER WINDSHIELD & SOME UPPER DOOR GLASS: MISSING							
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)							4

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。