

**INSPECTION SHEET 検品書**  
**EXCAVATOR バックホー**

|                 |                                        |      |         |                   |            |
|-----------------|----------------------------------------|------|---------|-------------------|------------|
| INSPECTION DATE | 2025/10/20                             | MAKE | HITACHI | MODEL             | ZX670LCH-3 |
| SERIAL          | HCM1J800H00020276                      |      | STAMP   | HCM1J800H00020276 |            |
| HR METER        | 8359                                   | HR   | YEAR    | YR                |            |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      | SHOE    | 650G              |            |

|                                              |                                                                              |
|----------------------------------------------|------------------------------------------------------------------------------|
| <b>ENGINE : MODEL</b> 6WG1 <b>S/N</b> 607725 |                                                                              |
| Oil leakage                                  | <input checked="" type="radio"/> FAIR · Attn                                 |
| Blow-By                                      | <input checked="" type="radio"/> FAIR · Attn A LITTLE · MIDDLE · SEVERE      |
| Sound                                        | <input checked="" type="radio"/> FAIR · Attn                                 |
| Oil                                          | <input checked="" type="radio"/> FAIR · Attn                                 |
| Exhaust Color                                | <input checked="" type="radio"/> FAIR · Attn                                 |
| US EPA                                       | <input checked="" type="radio"/> YES · NO                                    |
| <b>MAIN PUMP</b>                             |                                                                              |
| Sound                                        | <input checked="" type="radio"/> FAIR · Attn                                 |
| Oil leakage                                  | <input checked="" type="radio"/> FAIR · Attn にじみあり OIL OOZING                |
| Power                                        | <input checked="" type="radio"/> FAIR · Attn                                 |
| <b>COOLING SYSTEM</b>                        |                                                                              |
| Radiator                                     | <input checked="" type="radio"/> FAIR · Attn                                 |
| Oil Cooler                                   | <input checked="" type="radio"/> FAIR · Attn                                 |
| <b>OPERATING SYSTEM</b>                      |                                                                              |
| Swing                                        | <input checked="" type="radio"/> FAIR · Attn ガタあり SWING: LOOSE               |
| Travel                                       | <input checked="" type="radio"/> FAIR · Attn                                 |
| <b>INTERIOR See Photos. 写真参照</b>             |                                                                              |
| INTERIOR COND.                               | CLEAN · <input checked="" type="radio"/> FAIR · DIRTY                        |
| Operator's Seat                              | <input checked="" type="radio"/> FAIR · Attn 破れあり TORN                       |
| Glasses                                      | <input checked="" type="radio"/> FAIR · Attn Fガラス上下割れあり WINDSHIELDS: CRACKED |
| AirCon                                       | <input checked="" type="radio"/> A/C · H/C · H only · C only · None          |
| <b>BOOM / ARM / BKT</b>                      |                                                                              |
| Boom                                         | <input checked="" type="radio"/> FAIR · Attn                                 |
| Boom Cylinder                                | <input checked="" type="radio"/> FAIR · Attn                                 |
| Arm                                          | <input checked="" type="radio"/> FAIR · Attn                                 |
| Arm Cylinder                                 | <input checked="" type="radio"/> FAIR · Attn                                 |
| ATTACHMENT                                   | <input checked="" type="radio"/> FAIR · Attn                                 |
| BKT Cylinder                                 | <input checked="" type="radio"/> FAIR · Attn                                 |

|                                                                             |                                                                              |
|-----------------------------------------------------------------------------|------------------------------------------------------------------------------|
| <b>UNDERCARRIAGE : See Photos. 写真参照</b>                                     |                                                                              |
| <b>RUST</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)         | 4                                                                            |
| <b>COMMENT</b>                                                              |                                                                              |
|                                                                             |                                                                              |
| BKT                                                                         | <input checked="" type="radio"/> STD / SLOPE / NARROW / SKELETON / OTHER ( ) |
| Lever                                                                       | LONG · <input checked="" type="radio"/> WRIST                                |
| Multi                                                                       | MULTI · 2 · <input checked="" type="radio"/> NO                              |
| ARM-CRANE                                                                   | YES · <input checked="" type="radio"/> NO                                    |
| BLADE                                                                       | YES · <input checked="" type="radio"/> NO                                    |
| OFFSET                                                                      | YES · <input checked="" type="radio"/> NO                                    |
| OFFSET Cylinder                                                             | FAIR · Attn                                                                  |
| Piping                                                                      | <input checked="" type="radio"/> YES · NO Breaker only · Multi 5 *1          |
| <b>COMMENT</b>                                                              |                                                                              |
| *1 ホース1本欠 SOME HOSE: MISSING                                                |                                                                              |
|                                                                             |                                                                              |
| <b>RUST of BODY</b> (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) | 4                                                                            |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。