

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/1	MAKE	HITACHI	MODEL	ZX135US-3
SERIAL	HCM1R400E00084448		STAMP	HCM1R400E00084448	
HR METER	7726	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL	4JJ1	S/N	119351
Oil leakage	FAIR · Attn		
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR · Attn		
Oil	FAIR · Attn		
Exhaust Color	FAIR · Attn		
US EPA	YES · NO	文字切れている STICKER: PARTLY BROKEN	

MAIN PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	

OPERATING SYSTEM

Swing	FAIR・Attn	ガタあり SWING: LOOSE
Travel	FAIR・Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN	FAIR	DIRTY
Operator's Seat	FAIR	Attn	破れあり TORN
Glasses	FAIR	Attn	
AirCon	A/C	H/C	H only C only None

BOOM / ARM / BKT

Boom	FAIR	Attn	
Boom Cylinder	FAIR	Attn	
Arm	FAIR	Attn	ガタあり LOOSE
Arm Cylinder	FAIR	Attn	
ATTACHMENT	FAIR	Attn	
BKT Cylinder	FAIR	Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
---	----------

COMMENT

両側トラックフレーム補修跡あり TRACK FRAMES: REPAIRED

BKT (STD / SLOPE / NARROW / SKELETON / OTHER()

Lever	LONG ▪ WRIST
-------	---------------------

Multi	MULTI · 2 · NO
-------	-----------------------

ARM-CRANE	☒ YES	☐ NO
-----------	--------------------------------------	--------------------------

BLADE	☒ YES • NO	
-------	---	--

OFFSET	YES	☒ NO
--------	-----	-------------------------------------

OFFSET Cylinder	FAIR ▪ Attn	
-----------------	-------------	--

Piping	YES • NO	Breaker only • Multi
--------	-----------------	-----------------------------

COMMENT

バッテリーチャージランプ点灯あり CHARGE LAMP: ON

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **4**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。