

INSPECTION SHEET 検品書  
EXCAVATOR バックホー

|                 |                                        |      |         |       |           |
|-----------------|----------------------------------------|------|---------|-------|-----------|
| INSPECTION DATE | 2025/10/29                             | MAKE | KOMATSU | MODEL | PC38UU-2E |
| SERIAL          | 5144                                   |      |         | STAMP | 5144      |
| HR METER        | E5526                                  | HR   | YEAR    | YR    |           |
| CAB/CNP         | ROPS CAB / CAB / ROPS CNP / CNP / NONE |      |         | SHOE  | 300R      |

| ENGINE : MODEL            |                                    | S/N                            |
|---------------------------|------------------------------------|--------------------------------|
| Oil leakage               | FAIR · Attn                        |                                |
| Blow-By                   | FAIR · Attn                        | A LITTLE · MIDDLE · SEVERE     |
| Sound                     | FAIR · Attn                        |                                |
| Oil                       | FAIR · Attn                        |                                |
| Exhaust Color             | FAIR · Attn                        |                                |
| US EPA                    | YES · NO                           |                                |
| MAIN PUMP                 |                                    |                                |
| Sound                     | FAIR · Attn                        |                                |
| Oil leakage               | FAIR · Attn                        |                                |
| Power                     | FAIR · Attn                        |                                |
| COOLING SYSTEM            |                                    |                                |
| Radiator                  | FAIR · Attn                        | 穴、水漏れあり HOLES, COOLANT LEAKING |
| Oil Cooler                | FAIR · Attn                        |                                |
| OPERATING SYSTEM          |                                    |                                |
| Swing                     | FAIR · Attn                        |                                |
| Travel                    | FAIR · Attn                        | 2速不良 2nd GEAR: MALFUNCTION     |
| INTERIOR See Photos. 写真参照 |                                    |                                |
| INTERIOR COND.            | CLEAN · FAIR · DIRTY               |                                |
| Operator's Seat           | FAIR · Attn                        | 破れあり HUGE CUTS                 |
| Glasses                   | FAIR · Attn                        |                                |
| AirCon                    | A/C · H/C · H only · C only · None |                                |
| BOOM / ARM / BKT          |                                    |                                |
| Boom                      | FAIR · Attn                        |                                |
| Boom Cylinder             | FAIR · Attn                        |                                |
| Arm                       | FAIR · Attn                        |                                |
| Arm Cylinder              | FAIR · Attn                        | 油漏れあり OIL LEAKING              |
| ATTACHMENT                | FAIR · Attn                        |                                |
| BKT Cylinder              | FAIR · Attn                        | 油漏れ大 SEVERE OIL LEAKING        |

|                                                                                                                             |                                            |                      |
|-----------------------------------------------------------------------------------------------------------------------------|--------------------------------------------|----------------------|
| UNDERCARRIAGE :                                                                                                             |                                            | See Photos. 写真参照     |
| RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                                                                |                                            | 3                    |
| COMMENT                                                                                                                     |                                            |                      |
| 左右トラックローラー1個不良<br>SOME TRACK ROLLER EACH TRACK: MALFUNCTION                                                                 |                                            |                      |
|                                                                                                                             |                                            |                      |
| BKT                                                                                                                         | STD / SLOPE / NARROW / SKELETON / OTHER( ) |                      |
| Lever                                                                                                                       | LONG · WRIST                               |                      |
| Multi                                                                                                                       | MULTI · 2 · NO                             |                      |
| ARM-CRANE                                                                                                                   | YES · NO                                   |                      |
| BLADE                                                                                                                       | YES · NO                                   |                      |
| OFFSET                                                                                                                      | YES · NO                                   |                      |
| OFFSET Cylinder                                                                                                             | FAIR · Attn                                |                      |
| Piping                                                                                                                      | YES · NO                                   | Breaker only · Multi |
| COMMENT                                                                                                                     |                                            |                      |
| E/G掛けている間ずっと警告音あり<br>WARNING SOUNDS: ON DURING ENGINE RUNNING<br>ファンベルトなし FAN BELT: MISSING<br>HRメーターストップ HR METER: STOPPED |                                            |                      |
|                                                                                                                             |                                            |                      |
|                                                                                                                             |                                            |                      |
|                                                                                                                             |                                            |                      |
|                                                                                                                             |                                            |                      |
|                                                                                                                             |                                            |                      |
|                                                                                                                             |                                            |                      |
|                                                                                                                             |                                            |                      |
|                                                                                                                             |                                            |                      |
| RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)                                                        |                                            | 3                    |

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。