

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/10/6	MAKE	KOMATSU	MODEL	D21P-7
SERIAL	76640			STAMP	D207-76640
HR METER	5563	HR	SHOE	500LGP	YEAR 1993 YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL 4D95S-1 S/N 157220	
Oil leakage	☒ FAIR · Attn
Blow-By	☒ FAIR · Attn A LITTLE · MIDDLE · SEVERE
Sound	☒ FAIR · Attn
Oil	☒ FAIR · Attn
Exhaust Color	☒ FAIR · Attn
US EPA	YES · ☒ NO
OPERATION PUMP	
Sound	☒ FAIR · Attn
Oil leakage	☒ FAIR · Attn
Power	☒ FAIR · Attn
COOLING SYSTEM	
Radiator	☒ FAIR · Attn
Oil Cooler	☒ FAIR · Attn
TRANSMISSION & TRAVEL	
T/M TYPE	☒ PS · DD DIFF. STEERING YES · ☒ NO
Transmission	☒ FAIR · Attn
Travel	☒ FAIR · Attn
INTERIOR See Photos. 写真参照	
INTERIOR COND.	CLEAN · ☒ FAIR · DIRTY
Operator's Seat	☒ FAIR · Attn
Glasses	FAIR · Attn
AirCon	A/C · H/C · H only · C only · ☒ None
BLADE & CYLINDERS	
BLADE	☒ FAIR · Attn
CYLD.(R)	☒ FAIR · Attn
CYLD.(L)	☒ FAIR · Attn
TILT CYLD	☒ FAIR · Attn
ANGLE CYLD	☒ FAIR · Attn

UNDERCARRIAGE See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
COMMENT	
Ripper	MULTI · S/S Shanks PCS
Ripper CYLD.	FAIR · Attn
COMMENT	
左アームパッチあり LEFT ARM: PATCHED	
走行ロックブレーキ効きが悪い TRAVEL LOCK BRAKE: LOOSE	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。