

INSPECTION SHEET 検品書
TRUCKトラック

INSPECTION DATE	2025/10/6	MAKE	ISUZU	MODEL	FRR35C3S
SERIAL	FRR35C3S-7000716			STAMP	FRR35C3S-7000716
HR METER	UNKNOWN	HR	Odometer	51197	km
TIRE	225/80R17.5			YEAR	YR

ENGINE : MODEL		S/N	
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
US EPA	YES • NO		
OPERATION PUMP			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
COOLING SYSTEM			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
TRANSMISSION & TRAVEL			
T/M TYPE	AT • MT	*1	No. OF GEARS 6 GEARS
Transmission	FAIR • Attn		
4WD	4WD • 2WD		
Travel	FAIR • Attn		
FOOT BRAKE	FAIR • Attn		
PARKING BRAKE	FAIR • Attn		
INTERIOR See Photos. 写真参照			
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn	破れあり CUT	
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • NONE		
OUTRIGGERS / JACK			
OUTRIGGERS	X • H		
CONDITION	FAIR • Attn		
JACK	FAIR • Attn		

UNDERCARRIAGE : See Photos. 写真参照			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR	FAIR • WORN • UNEVEN WEAR		
COMMENT			
BODY			
CATEGORY	散水車 WATER SPRINKLER TRUCK		
MAKE	KYOKUTO		
MODEL	LH04-30R	SERIAL	02L064016T
CONDITION	FAIR • Attn	散水不良 NOT WATERING	
MAIN FRAME	FAIR • Attn		
CRANE			
MAKE			
MODEL		SERIAL	
No. of Section	SECTIONS		
HOOK			
RADIO CONTROL	YES • NO		
COMMENT			
*1 入りづらい HARD TO SHIFT IN ANY GEARS			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。