

INSPECTION SHEET 検品書  
TRUCKトラック

INSPECTION DATE	2025/10/6	MAKE	ISUZU	MODEL	FRR35C3S
SERIAL	FRR35C3S-7000753			STAMP	FRR35C3S-7000753
HR METER	UNKNOWN	HR	Odometer	56920	km
TIRE	225/80R17.5			YEAR	YR

<b>ENGINE : MODEL</b>		<b>S/N</b>	
Oil leakage	FAIR • Attn		
Blow-By	FAIR • Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR • Attn		
Oil	FAIR • Attn		
Exhaust Color	FAIR • Attn		
US EPA	YES • NO		
<b>OPERATION PUMP</b>			
Sound	FAIR • Attn		
Oil leakage	FAIR • Attn		
Power	FAIR • Attn		
<b>COOLING SYSTEM</b>			
Radiator	FAIR • Attn		
Oil Cooler	FAIR • Attn		
<b>TRANSMISSION &amp; TRAVEL</b>			
T/M TYPE	AT • MT	No. OF GEARS	6 GEARS
Transmission	FAIR • Attn		
4WD	4WD • 2WD		
Travel	FAIR • Attn		
FOOT BRAKE	FAIR • Attn		
PARKING BRAKE	FAIR • Attn		
<b>INTERIOR See Photos. 写真参照</b>			
INTERIOR COND.	CLEAN • FAIR • DIRTY		
Operator's Seat	FAIR • Attn		
Glasses	FAIR • Attn		
AirCon	A/C • H/C • H only • C only • NONE		
<b>OUTRIGGERS / JACK</b>			
OUTRIGGERS	X • H		
CONDITION	FAIR • Attn		
JACK	FAIR • Attn		

<b>UNDERCARRIAGE : See Photos. 写真参照</b>			
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3
TIRE WEAR		FAIR • WORN • UNEVEN WEAR	
<b>COMMENT</b>			
<b>BODY</b>			
CATEGORY	散水車 WATER SPRINKLER TRUCK		
MAKE	SHIN MAYWA		
MODEL	LSE40-4	SERIAL	F308336617
CONDITION	FAIR • Attn	散水不良 NOT WATERING	
MAIN FRAME	FAIR • Attn		
<b>CRANE</b>			
MAKE			
MODEL		SERIAL	
No. of Section	SECTIONS		
HOOK			
RADIO CONTROL	YES • NO		
<b>COMMENT</b>			
散水ポンプE/G掛からない ENGINE DRIVEN PUMP: UNABLE TO WORK			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)			3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.  
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。