

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/2	MAKE	KOMATSU	MODEL	WA200-6		
SERIAL	71087			STAMP	WA105-71087		
HR METER	8752	HR	Odometer	29234	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25 12PR (SNOW)		

ENGINE :		MODEL	4D107E-1	S/N	26558244	
Oil leakage	FAIR	Attn				
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE			
Sound	FAIR	Attn				
Oil	FAIR	Attn				
Exhaust Color	FAIR	Attn				
US EPA	YES	NO				
OPERATION PUMP						
Sound	FAIR	Attn				
Oil leakage	FAIR	Attn				
Power	FAIR	Attn				
COOLING SYSTEM						
Radiator	FAIR	Attn				
Oil Cooler	FAIR	Attn				
TRANSMISSION & TRAVEL						
T/M TYPE	PS	DD				
Transmission	FAIR	Attn				
Travel	FAIR	Attn				
FOOT BRAKE	FAIR	Attn				
PARKING BRAKE	FAIR	Attn				
INTERIOR See Photos. 写真参照						
INTERIOR COND.	CLEAN	FAIR	DIRTY			
Operator's Seat	FAIR	Attn	汚れ、穴あり DIRTY, HOLES			
Glasses	FAIR	Attn				
AirCon	A/C	H/C	H only	C only	None	
FRONT & CYLINDERS						
Arm	FAIR	Attn	*1			
Bell crank	FAIR	Attn				
Bucket	FAIR	Attn				
Articulate	FAIR	Attn				
UNDERCARRIAGE : See Photos. 写真参照						
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4	
TIRE WEAR					FAIR · WORN · UNEVEN WEAR	
COMMENT						
右Rタイヤ1本パンクあり REAR RIGHT TIRE: FLAT						
STEERING TYPE						WHEEL STEERING / COMMAND STEERING / LEVER STEERING
RIDE CONTROL					YES · NO	
ATTACHMENTS						
STD BKT					YES · OTHER	
BLADE					YES · NO Piping for Tilt YES · NO	
COMMENT						
*1 左右シリンダー油漏れあり CYLINDERS: OIL LEAKING						
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。