

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/6	MAKE	HITACHI	MODEL	LX30-7		
SERIAL	HFK4E200P00005024			STAMP	F37-05024		
HR METER	5512	HR	Odometer	—	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	15.5/60-18		

ENGINE : MODEL		D1503	S/N	06G0636
Oil leakage	FAIR · Attn			
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR · Attn			
Oil	FAIR · Attn			
Exhaust Color	FAIR · Attn			
US EPA	YES · NO			

OPERATION PUMP

Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	
Power	FAIR · Attn	

COOLING SYSTEM

Radiator	FAIR	Attn	
Oil Cooler	FAIR	Attn	

TRANSMISSION & TRAVEL

T/M TYPE	PS · DD	
Transmission	FAIR · Attn	
Travel	FAIR · Attn	
FOOT BRAKE	FAIR · Attn	
PARKING BRAKE	FAIR · Attn	

INTERIOR See Photos. 写真参照

INTERIOR COND.	CLEAN ・ FAIR ・ DIRTY				
Operator's Seat	FAIR ・ Attn	破れあり CUT			
Glasses	FAIR ・ Attn				
AirCon	A/C ・ H/C ・ H only ・ C only ・ None				

FRONT & CYLINDERS

Arm	FAIR · Attn	*1
Bell crank	FAIR · Attn	
Bucket	FAIR · Attn	
Articulate	FAIR · Attn	

UNDERCARRIAGE : See Photos. 写真参照

RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
---	----------

TIRE WEAR (FAIR • WORN • UNEVEN WEAR)

COMMENT

右F、左Rタイヤ劣化小

FRONT RIGHT & REAR LEFT TIRES: DETERIORATED

STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING

RIDE CONTROL	YES	▪	(NO)
--------------	-----	---	------

ATTACHMENTS

STD BKT	YES • OTHER	
---------	-------------	--

BLADE	YES	☒ NO	Piping for Tilt	YES	☒ NO
-------	-----	-------------------------------------	-----------------	-----	-------------------------------------

COMMENT

*1 左シリンダー油漏れ小 LEFT CYLINDER: OIL LEAKING

RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED) **3**

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。