

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/7	MAKE	HITACHI	MODEL	ZX75US-3
SERIAL	HCM1P300C00062720		STAMP	HCM1P300C00062720	
HR METER	2814	HR	YEAR	YR	
CAB/CNP	ROPS CAB / <u>CAB</u> / ROPS CNP / CNP / NONE		SHOE	450G PADS	

ENGINE : MODEL		4LE2	S/N	826760
Oil leakage	<u>FAIR</u> • Attn			
Blow-By	<u>FAIR</u> • Attn	A LITTLE • MIDDLE • SEVERE		
Sound	<u>FAIR</u> • Attn			
Oil	<u>FAIR</u> • Attn			
Exhaust Color	<u>FAIR</u> • Attn			
US EPA	YES • <u>NO</u>			
MAIN PUMP				
Sound	<u>FAIR</u> • Attn			
Oil leakage	<u>FAIR</u> • Attn			
Power	<u>FAIR</u> • Attn			
COOLING SYSTEM				
Radiator	<u>FAIR</u> • Attn			
Oil Cooler	<u>FAIR</u> • Attn			
OPERATING SYSTEM				
Swing	<u>FAIR</u> • Attn			
Travel	<u>FAIR</u> • Attn			
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN • <u>FAIR</u> • DIRTY			
Operator's Seat	FAIR • <u>Attn</u>	穴あり CUTS		
Glasses	FAIR • <u>Attn</u>	*1		
AirCon	<u>A/C</u> • H/C • H only • C only • None			
BOOM / ARM / BKT				
Boom	<u>FAIR</u> • Attn			
Boom Cylinder	<u>FAIR</u> • Attn			
Arm	<u>FAIR</u> • Attn			
Arm Cylinder	<u>FAIR</u> • Attn			
ATTACHMENT	<u>FAIR</u> • Attn			
BKT Cylinder	<u>FAIR</u> • Attn			

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	4
COMMENT	
BKT	<u>STD</u> / SLOPE / NARROW / SKELETON / OTHER ()
Lever	LONG • <u>WRIST</u>
Multi	MULTI • 2 • <u>NO</u>
ARM-CRANE	YES • <u>NO</u>
BLADE	YES • <u>NO</u>
OFFSET	YES • <u>NO</u>
OFFSET Cylinder	FAIR • Attn
Piping	<u>YES</u> • NO Breaker only • Multi 5
COMMENT	
付属品: 杭打抜機 PILE EXTRACTOR (MAKE: NPK HP-2SX) AS SPARE	
*1 F上傷あり(写真には映らない)	
*1 UPPER WINDSHIELD: SCRATCHED (UNVISIBLE IN THE PHOTOS)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
4	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。