

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/2	MAKE	KOMATSU	MODEL	PC200-8N1
SERIAL	353692		STAMP	KMTPC197K02353692	
HR METER	16935	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	600G	

ENGINE : MODEL		6D107E-1	S/N	26596375
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE *1	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
MAIN PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
OPERATING SYSTEM				
Swing	FAIR	Attn	ガタあり SWING: LOOSE	
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn	破れあり HUGE CUTS	
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only
None				
BOOM / ARM / BKT				
Boom	FAIR	Attn	パッチあり PATCHED	
Boom Cylinder	FAIR	Attn		
Arm	FAIR	Attn	ガタ、パッチあり LOOSE, PATCHED	
Arm Cylinder	FAIR	Attn		
ATTACHMENT	FAIR	Attn		
BKT Cylinder	FAIR	Attn	傷あり SCRATCHED	

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	3
COMMENT 左側ピンブッシュ割れ多数あり MANY LEFT PIN BUSHES: BROKEN 右側ピンブッシュ摩耗大 RIGHT PIN BUSHES: MUCH WORN	
BKT	(STD / SLOPE / NARROW / SKELETON / OTHER()
Lever	LONG ▪ (WRIST)
Multi	MULTI ▪ 2 ▪ (NO)
ARM-CRANE	YES ▪ (NO)
BLADE	YES ▪ (NO)
OFFSET	YES ▪ (NO)
OFFSET Cylinder	FAIR ▪ Attn
Piping	YES ▪ (NO) Breaker only ▪ Multi
COMMENT *1 オイル吐出しあり OIL SPURTING	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。