

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/7		MAKE	KOMATSU		MODEL	JH90EV	
SERIAL	0357			STAMP	NOT FOUND			
HR METER	UNKNOWN	HR	Odometer	56924		km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	23.5-25 (SNOW, SPIKE)			

ENGINE : MODEL		S/N
Oil leakage	FAIR	Attn
Blow-By	FAIR	Attn A LITTLE · MIDDLE · SEVERE
Sound	FAIR	Attn
Oil	FAIR	Attn
Exhaust Color	FAIR	Attn
US EPA	YES	NO
OPERATION PUMP		
Sound	FAIR	Attn
Oil leakage	FAIR	Attn
Power	FAIR	Attn
COOLING SYSTEM		
Radiator	FAIR	Attn
Oil Cooler	FAIR	Attn
TRANSMISSION & TRAVEL		
T/M TYPE	PS	DD
Transmission	FAIR	Attn
Travel	FAIR	Attn *1
FOOT BRAKE	FAIR	Attn *2
PARKING BRAKE	FAIR	Attn 不良 MALFUNCTION
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN	FAIR · DIRTY
Operator's Seat	FAIR	Attn *3
Glasses	FAIR	Attn 左サイド割れ大 LEFT SIDE GLASS: BROKEN
AirCon	A/C · H/C	H only · C only · None
FRONT & CYLINDERS		
Arm	FAIR	Attn *4
Bell crank	FAIR	Attn
Bucket	FAIR	Attn
Articulate	FAIR	Attn *5

UNDERCARRIAGE : See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	2
TIRE WEAR	FAIR · WORN · UNEVEN WEAR
COMMENT	
タイヤ4本劣化小 TIRES: DETERIORATED	
STEERING TYPE WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL	YES · NO
ATTACHMENTS	
STD BKT	YES · OTHER
BLADE	YES · NO Piping for Tilt YES · NO
COMMENT	
エア溜まらない AIR: UNABLE TO STORE	
左右サイドカバー欠 SIDE COVERS: MISSING	
メインポンプに入る配管油漏れあり(吸着マットあり)	
SOME PIPE WITH MAIN PUMP: OIL LEAKING (W/ABSORPTION MAT)	
ヒーター不良 HEATER: MALFUNCTION	
*1 遅い、2～4速ギア入らない	
*1 SLOW TRAVELING (2nd TO 4th GEARS: UNABLE TO SHIFT IN)	
*2 不良、左ブレーキペダル固着あり MALFUNCTION, LEFT PEDAL: STUCK	
*3 破れ大、アームレスト破損あり CUTS, ARMRESTS: BROKEN	
*4 左右シリンダー油漏れあり(吸着マットあり)	
*4 CYLINDERS: OIL LEAKING (W/ABSORPTION MAT)	
*5 左シリンダー油漏れあり(吸着マットあり)	
*5 LEFT CYLINDER: OIL LEAKING (W/ABSORPTION MAT)	
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)	
1	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。