

INSPECTION SHEET 検品書
WHEEL LOADER タイヤショベル

INSPECTION DATE	2025/10/8	MAKE	HITACHI	MODEL	ZW140		
SERIAL	RYU4FC00V00005329			STAMP	S61-05329		
HR METER	6812	HR	Odometer	36872	km	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE			TIRE SIZE	17.5-25 (SNOW, SPIKE)		

ENGINE : MODEL		QB4	S/N	26554776
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE • MIDDLE • SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
OPERATION PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	PS	DD		
Transmission	FAIR	Attn		
Travel	FAIR	Attn		
FOOT BRAKE	FAIR	Attn		
PARKING BRAKE	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C	H only	C only None
FRONT & CYLINDERS				
Arm	FAIR	Attn		
Bell crank	FAIR	Attn		
Bucket	FAIR	Attn		
Articulate	FAIR	Attn		

UNDERCARRIAGE :		See Photos. 写真参照	
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	
TIRE WEAR		FAIR • WORN • UNEVEN WEAR	
COMMENT			
タコメーター TACHOMETER: 36436km			
STEERING TYPE		WHEEL STEERING / COMMAND STEERING / LEVER STEERING	
RIDE CONTROL		YES • NO	
ATTACHMENTS			
STD BKT		YES • OTHER	
BLADE		YES • NO Piping for Tilt YES • NO	
COMMENT			
ワンタッチ付 W/ONE-TOUCH			
付属品:マルチプラウ(合わないので取付不可)			
MULTI PLOW AS SPARE (UNABLE TO ATTACH TO THIS MACHINE)			
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。