

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/29	MAKE	KOMATSU	MODEL	PC138US-8
SERIAL	25846		STAMP	KMTPC189C01025846	
HR METER	19341	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G PADS	

ENGINE : MODEL		S/N
Oil leakage	FAIR · Attn	
Blow-By	FAIR · Attn	A LITTLE · MIDDLE · SEVERE
Sound	FAIR · Attn	
Oil	FAIR · Attn	
Exhaust Color	FAIR · Attn	
US EPA	YES · NO	
MAIN PUMP		
Sound	FAIR · Attn	
Oil leakage	FAIR · Attn	油汚れあり OIL STAINS
Power	FAIR · Attn	
COOLING SYSTEM		
Radiator	FAIR · Attn	
Oil Cooler	FAIR · Attn	
OPERATING SYSTEM		
Swing	FAIR · Attn	ガタあり SWING: LOOSE
Travel	FAIR · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · FAIR · DIRTY	
Operator's Seat	FAIR · Attn	破れあり CUT
Glasses	FAIR · Attn	
AirCon	A/C · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	FAIR · Attn	
Boom Cylinder	FAIR · Attn	
Arm	FAIR · Attn	
Arm Cylinder	FAIR · Attn	
ATTACHMENT	FAIR · Attn	
BKT Cylinder	FAIR · Attn	

UNDERCARRIAGE :						See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)								3			
COMMENT											
シューパッド摩耗大、剥がれ多数あり RUBBER PADS: ALMOST GONE											
BKT	STD / SLOPE / NARROW / SKELETON							(OTHER)			
Lever	LONG		▪		(WRIST)						
Multi	(MULTI)		▪		2		▪		NO		
ARM-CRANE	YES		▪		(NO)						
BLADE	(YES)		▪		NO						
OFFSET	YES		▪		(NO)						
OFFSET Cylinder	FAIR		▪		Attn						
Piping	(YES)		▪		NO		Breaker only		▪		Multi
									5		
COMMENT											
アタッチメント:回転式フォークグラブ											
ATTACHMENT: ROTATABLE FORK GRAB											
コントロールバルブ油汚れあり CONTROL VALVE: OIL STAINS											
A/Cエラー表示あり A/C ERROR DISPLAY											
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)										3	

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。