

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/6/27	MAKE	KOMATSU	MODEL	PC228US-2
SERIAL	15780		STAMP	PC228-015780	
HR METER	14131		HR	YEAR	YR
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	800G	

ENGINE :		MODEL	6D102E-1	S/N	26269457
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE ・ MIDDLE ・ SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
MAIN PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
OPERATING SYSTEM					
Swing	FAIR	Attn	*1		
Travel	FAIR	Attn	*2		
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn	穴、破れあり HOLE, MUCH WORN		
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BOOM / ARM / BKT					
Boom	FAIR	Attn			
Boom Cylinder	FAIR	Attn	右シリンダーサビあり RIGHT CYLINDER: RUSTY		
Arm	FAIR	Attn			
Arm Cylinder	FAIR	Attn			
ATTACHMENT	FAIR	Attn	ガタあり LOOSE		
BKT Cylinder	FAIR	Attn			

UNDERCARRIAGE : See Photos. 写真参照					
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3
COMMENT					
BKT	(STD)	SLOPE / NARROW / SKELETON / OTHER()			
Lever	LONG	▪	(WRIST)		
Multi	MULTI	▪	2	▪	(NO)
ARM-CRANE	(YES)	▪	NO		
BLADE	YES	▪	(NO)		
OFFSET	YES	▪	(NO)		
OFFSET Cylinder	FAIR	▪	Attn		
Piping	(YES)	▪	NO	Breaker only ▪ Multi	5
COMMENT					
回転灯カバー割れあり ROTARY LAMP COVER: CRACKED					
燃料タンク内サビあり INSIDE OF FUEL TANK: RUSTY					
スピーカー破損あり SPEAKER: DAMAGED					
A/Cぬるい A/C: MALFUNCTION					
*1 スムーズではなく違和感、ガタあり RATTLING, SWING: LOOSE					
*2 下側ドア窓クラックあり LOWER DOOR GLASS: CRACKED					
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)					3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。