

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/10/24	MAKE	KOMATSU	MODEL	D65PX-15E0
SERIAL	71129			STAMP	KMT0D100E01071129
HR METER	7918	HR	SHOE	610G	YEAR 2008 YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE :		MODEL	6D114E-3	S/N	26856441
Oil leakage	FAIR	Attn			
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE		
Sound	FAIR	Attn			
Oil	FAIR	Attn			
Exhaust Color	FAIR	Attn			
US EPA	YES	NO			
OPERATION PUMP					
Sound	FAIR	Attn			
Oil leakage	FAIR	Attn			
Power	FAIR	Attn			
COOLING SYSTEM					
Radiator	FAIR	Attn			
Oil Cooler	FAIR	Attn			
TRANSMISSION & TRAVEL					
T/M TYPE	PS	DD	DIFF. STEERING	YES	NO
Transmission	FAIR	Attn			
Travel	FAIR	Attn			
INTERIOR See Photos. 写真参照					
INTERIOR COND.	CLEAN	FAIR	DIRTY		
Operator's Seat	FAIR	Attn			
Glasses	FAIR	Attn			
AirCon	A/C	H/C	H only	C only	None
BLADE & CYLINDERS					
BLADE	FAIR	Attn			
CYLD.(R)	FAIR	Attn	自然降下大 MUCH HYDRAULIC DRIFT		
CYLD.(L)	FAIR	Attn	自然降下大 MUCH HYDRAULIC DRIFT		
TILT CYLD	FAIR	Attn			
ANGLE CYLD	FAIR	Attn			

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。