

INSPECTION SHEET 検品書
BULLDOZER ブルドーザー

INSPECTION DATE	2025/10/21	MAKE	KOMATSU	MODEL	D37PX-24
SERIAL	85667			STAMP	KMT0D131HLA085667
HR METER	2495	HR	SHOE	600LGP	YEAR 2020 YR
BLADE	STRAIGHT / ST/TILT / PAT / ANGLE / OTHER			CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE

ENGINE : MODEL		4D95LE-7	S/N	817603
Oil leakage	FAIR	Attn		
Blow-By	FAIR	Attn	A LITTLE · MIDDLE · SEVERE	
Sound	FAIR	Attn		
Oil	FAIR	Attn		
Exhaust Color	FAIR	Attn		
US EPA	YES	NO		
OPERATION PUMP				
Sound	FAIR	Attn		
Oil leakage	FAIR	Attn		
Power	FAIR	Attn		
COOLING SYSTEM				
Radiator	FAIR	Attn		
Oil Cooler	FAIR	Attn		
TRANSMISSION & TRAVEL				
T/M TYPE	PS	DD	DIFF. STEERING	YES · NO
Transmission	FAIR	Attn		
Travel	FAIR	Attn		
INTERIOR See Photos. 写真参照				
INTERIOR COND.	CLEAN	FAIR	DIRTY	
Operator's Seat	FAIR	Attn		
Glasses	FAIR	Attn		
AirCon	A/C	H/C · H only · C only · None		
BLADE & CYLINDERS				
BLADE	FAIR	Attn		
CYLD.(R)	FAIR	Attn		
CYLD.(L)	FAIR	Attn		
TILT CYLD	FAIR	Attn		
ANGLE CYLD	FAIR	Attn		

[illegible]

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.
この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。