

INSPECTION SHEET 検品書
EXCAVATOR バックホー

INSPECTION DATE	2025/10/29	MAKE	KATO	MODEL	HD510
SERIAL	NO PLATE		STAMP	5523	
HR METER	18386	HR	YEAR	YR	
CAB/CNP	ROPS CAB / CAB / ROPS CNP / CNP / NONE		SHOE	500G	

ENGINE : MODEL		S/N
Oil leakage	(FAIR) · Attn	
Blow-By	(FAIR) · Attn	A LITTLE · MIDDLE · SEVERE
Sound	(FAIR) · Attn	
Oil	(FAIR) · Attn	
Exhaust Color	(FAIR) · Attn	
US EPA	YES · (NO)	
MAIN PUMP		
Sound	(FAIR) · Attn	
Oil leakage	(FAIR) · Attn	
Power	(FAIR) · Attn	
COOLING SYSTEM		
Radiator	(FAIR) · Attn	
Oil Cooler	(FAIR) · Attn	
OPERATING SYSTEM		
Swing	(FAIR) · Attn	ガタあり SWING: LOOSE
Travel	(FAIR) · Attn	
INTERIOR See Photos. 写真参照		
INTERIOR COND.	CLEAN · (FAIR) · DIRTY	
Operator's Seat	(FAIR) · Attn	
Glasses	FAIR · (Attn) *1	
AirCon	(A/C) · H/C · H only · C only · None	
BOOM / ARM / BKT		
Boom	(FAIR) · Attn	
Boom Cylinder	FAIR · (Attn)	左右にじみあり CYLINDERS: OIL OOZING
Arm	(FAIR) · Attn	ガタあり LOOSE
Arm Cylinder	FAIR · (Attn)	油漏れ小 OIL LEAKING
ATTACHMENT	(FAIR) · Attn	
BKT Cylinder	FAIR · (Attn)	油漏れあり OIL LEAKING

UNDERCARRIAGE :		See Photos. 写真参照
RUST (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3
COMMENT		
BKT	STD / SLOPE / NARROW / SKELETON / (OTHER) FORK GRAB)	
Lever	LONG · (WRIST)	
Multi	MULTI · 2 · (NO)	
ARM-CRANE	YES · (NO)	
BLADE	YES · (NO)	
OFFSET	YES · (NO)	
OFFSET Cylinder	FAIR · Attn	
Piping	YES · (NO)	Breaker only · Multi
COMMENT		
全体的にホースひび割れあり MANY HYDRAULIC HOSES: MUCH CRACKED		
モニター表示されない MONITOR: NOT DISPLAYING		
A/C電源入らない A/C: UNABLE TO TURN ON		
*1 F下部欠、Fガラス上がったまま固着あり		
*1 LOWER WINDSHIELD: MISSING,		
UPPER WINDSHIELD: STUCK AT A CEILING POSITION		
RUST of BODY (5: NONE, 4: A LITTLE, 3: MIDDLE, 2: MUCH, 1: CORRODED)		3

This inspection information is for reference only at "the inspection date" by SOGO. NOT to guarantee the condition of the actual machine.

この査定情報は『点検日時点』での参考資料であり、実際の機械の状態を保証するものではありません。